

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21009099/UTF3N2**Date:** 27/09/2021REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | 1001515619 |
| Claimant Vehicle No : | YP4224P | Insured Vehicle No : | YQ2890Z |
| Date of Loss: | 27/08/2021 | Nature of Claim: | TP |
| | | Claim No: | 261880 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------------|-------------|--------------|
| Reg No: | YP4224P | Engine No: | 4P10C18955 |
| Make & Model: | MITSUBISHI FEB21CR4SDEB, 3.0 D (M) | Chassis No: | FEB21CA20050 |
| Reg. Date: | 14/09/2016 (Man. Year: 2016) | Odometer: | 155725 km |
| Colour: | White | | |
| Engine Capacity: | 2998 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|----------------|
| Front Tyre Size: | 195R15 | Rear Tyre Size: | 195R15(D) |
| Front Left Side: | Austone 6 mm | Rear Left Side: | Austone 6/6 mm |
| Front Right Side: | Austone 6 mm | Rear Right Side: | Austone 6/6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 1,364.10 | 553.67 | 810.43 | 59.41 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 620.00 | 470.00 | 150.00 | 24.19 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 1,984.10 | 1,023.67 | 960.43 | 48.41 |
| Approved Total (Overridden) (S\$) | | 800.00 | | |
| Nett Amount (S\$) | 1,984.10 | 800.00 | 1,184.10 | 59.68 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 31/08/2021 | Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883 |
| Date Inspected: | 31/08/2021 Inspected At: | |
| Estimated Period of Repair: | 2.0 days | |

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | (Last Synchronised: 25 Sep 2021) | |
| Parts: | N/A | MITSUBISHI FEB21CR4SDEB 3.0 D (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for YP4224P) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------|----------------|------------|------------|
| 1 | 1 | | *FRONT RH CORNER PANEL GARNISH | Warped/Cracked | 474.60 F | *474.60 FL |
| 2 | 1 | | *FRONT RH SIGNAL LAMP | Cracked | 324.30 F | *263.63 FL |
| 3 | 1 | | *FRONT RH DOOR VIEW MIRROR BRACKET | Repair | 545.20 FS | *- FS |
| 4 | 1 | | *SET FRONT RH SIGNAL LAMP CLIPS | Not Necessary | 20.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|---------------|
| Sub Total (\$\$) | 1,364.10 | 738.23 |
| - List Item Discount on L Items 0.00/25.00% (\$\$) | 0.00 | 184.56 |
| Total Parts (\$\$) | 1,364.10 | 553.67 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|---------------|---------------|
| Labour Items | | | | |
| 1 | TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION | New | 30.00 | 20.00 |
| 2 | LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS | New | 300.00 | 250.00 |
| 3 | TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA | New | 250.00 | 200.00 |
| 4 | TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA | New | 40.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 620.00 | 470.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >