

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 47883

ROB No: 53291793 | Tel: 6741-1730 / 731 | Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: YP4224P210827

Estimate**Customer**

Name: MSIG Insurance (Singapore) Pte Ltd

Address: Motor Claims Department

4 Shenton Way #21-01

SGX Centre 2

Singapore 068807

Date: 30-08-21

Vehicle No: YP4224P

Model/Make: Mitsubishi

Canter FEB21CR4SDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh Corner Panel Garnish <i>waped/cu</i>	\$ 474.60	<i>263-63</i>
2	Signal Lamp <i>cu</i>	\$ 324.30	<i>250</i>
3	Signal Lamp Clips 01 set <i>cu</i>	\$ 20.00	<i>200</i>
4	Door View Mirror Bracket <i>cu</i>	\$ 545.20	<i>11X</i>
	To check all wiring & electrical component for proper function	\$ 30.00	<i>20</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 300.00	<i>250</i>
	To putty & spray painting & including touch up paint on accident affected	\$ 250.00	<i>200</i>
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 40.00	<i>11X</i>

Total Parts & Labour of estimate for damaged vehicle

\$ 1,984.10

Total amount in Lump Sum Basis for repaired vehicle

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

not Allowed
du
1/5 \$ 800
2 days
31/8/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

2.738.23
25%
2.553.67
2-470
1023.67
20%
818