



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2202685

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 11/05/2022
Reference CC4/LPC21009108/Aea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SGR 1919R
Insured Veh. SKX 2805A
Claim No. 20/21/21/VP05/024906
Policy No. Z20VP05027965
Accident Date 28/08/2021
Inspection Date 30/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21009108/Aea3q2	Date: 11/05/2022
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKX 2805A	Veh. Inspected	SGR 1919R	
Policy No.	Z20VP05027965	Coverage (\$)	0.00	
Claim No.	20/21/21/VP05/024906	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	30/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA CX-3	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6DK2W7AH0127524	Colour	BRONZE	
Odometer	114090 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R18	YOKOHAMA	6 mm	
L/H Front Tyre	215/50 R18	YOKOHAMA	6 mm	
R/H Rear Tyre	215/50 R18	YOKOHAMA	6 mm	
L/H Rear Tyre	215/50 R18	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/08/2021	Inspection Date	30/08/2021	
Survey held at	CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 1919R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILGATE	DENTED	1,090.00	1,090.00
1	REAR TAILGATE LOCK	DAMAGED	213.00	213.00
1	REAR TAILGATE INNER TRIM BOARD	CRACKED	217.00	217.00
2	REAR TAILGATE NUMBER PLATE LAMP @\$75.00	CRACKED	150.00	150.00
1	REAR TAILGATE LOCK SENSOR	DAMAGED	110.00	110.00
2	REAR TAILGATE LOCK OPEN SWITCH	DAMAGED	178.00	178.00
2	REAR TAILGATE LAMP @\$676.00	CUT	1,352.00	1,352.00
1	REAR TAILGATE EMBLEM LOGO	NECESSARY	55.00	55.00
1	REAR TAILGATE EMBLEM CX 3	NECESSARY	56.00	56.00
1	REAR BUMPER	DISTORTED	1,089.00	1,089.00
1	REAR BUMPER REINFORCEMENT	BENT	363.00	363.00
2	REAR BUMPER SIDE RETAINER @\$25.00	NECESSARY	50.00	50.00
2	REAR BUMPER REFLECTOR @\$145.00	CRACKED	290.00	290.00
2	REAR BUMPER REFLECTOR BRACKET @\$81.00	DAMAGED	162.00	162.00
1	REAR BUMPER LOWER CENTER BRACKET	DAMAGED	43.00	43.00
4	REAR BUMPER REVERSE SENSOR @\$136.00	DAMAGED (2 PCS ONLY)	544.00	272.00
1	REAR BUMPER REVERSE SENSOR WIRE HARNESS	NOT NECESSARY	120.00	-
1	REAR END PANEL	DENTED	486.00	486.00
1	REAR END PANEL TOP GARNISH	DEFORMED	87.00	87.00
2	REAR TAILLAMP @\$1505.00	O/S CUT	3,010.00	1,505.00
2	REAR TAILLAMP LOWER BRACKET	NOT NECESSARY	38.00	-
1	REAR EXHAUST MUFFLER	BENT	1,350.00	1,185.00
2	REAR EXHAUST MUFFLER RUBBER MOUNTING @\$35.00	NOT NECESSARY	70.00	-
1	REAR EXHAUST MUFFLER SHIELD	CRUMPLED	63.00	63.00
1	RH REAR WHEEL ARCH GARNISH	NOT NECESSARY	71.00	-
1	REAR BUMPER LOWER CENTER BRACKET (EXTENSION) (ADDITIONAL)	DAMAGED	96.00	96.00
2	SENSOR MODULE BRACKET @\$87.00 (ADDITIONAL)	CRACKED	174.00	174.00
1	REAR SPARE TYRE COMPARTMENT PANEL (ADDITIONAL)	BUCKLED	897.00	897.00
2	REAR FENDER AIR VENT @\$75.00 (ADDITIONAL)	CRACKED	150.00	150.00

Report Ref No. CC4/LPC21009108/Aea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR KEYLESS SENSOR (ADDITIONAL)	DAMAGED	112.00	112.00
2	REAR FENDER INNER TRIM BOARD @\$395.00 (ADDITIONAL)	O/S CRACKED	790.00	395.00
	LESS 20% DISCOUNT		-2,695.20	-2,168.00
			10,780.80	8,672.00
1	REAR REVERSE CAMERA (SN)	DAMAGED	756.00	400.00
	LESS 20% DISCOUNT		-151.20	-
			604.80	400.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	60.00
1	REAR TAILGATE WINDSCREEN GLASS SEALANT (SN)	NECESSARY	100.00	60.00
2	REAR TAILLAMP CLIPS @\$40.00 (SN)	NECESSARY	80.00	20.00
1	REAR NUMBER PLATE WITH CASING (SN)	CRACKED	60.00	60.00
1	SPARE TYRE COMPARTMENT PANEL INSULATION PAD (SN)	NECESSARY	300.00	200.00
			680.00	430.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING.		1,800.00	1,300.00
	LABOUR FOR SPRAY PAINTING.		1,200.00	1,100.00
	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS .		120.00	120.00
	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING.		250.00	80.00
	WIRING CHECK.		80.00	30.00
	LABOUR FOR REMOVE & RENEW REAR EXHAUST MUFFLER /TO REPAIR & STRAIGHTEN REAR EXHAUST PIPE.		300.00	80.00
	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS.		300.00	100.00
			4,050.00	2,810.00
	GRAND TOTAL		16,115.60	12,312.00

Report Ref No. CC4/LPC21009108/Aea3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,800.00
---	--	--	-----------------

Report Ref No. CC4/LPC21009108/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGR 1919R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGR 1919R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGR 1919R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

