

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009119/BGA3Q2**Date:** 16/08/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SJY5488T **Insured Vehicle No :** SLJ5273B
 Date of Loss: 27/08/2021 Nature of Claim: TP Claim No: MFL2021D0003679

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY5488T**
 Make & Model: BMW X1 SDRIVE18I, 1.5 LED NAV (A) Engine No: F880H453B38A15A
 Reg. Date: 17/05/2017 (Man. Year: 2017) Chassis No: WBAHS120505H48858
 Colour: Silver Odometer: 59115 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,879.89	3,578.11	1,301.78	26.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,160.00	520.00	30.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,559.89	4,738.11	1,821.78	27.77
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	6,559.89	3,800.00	2,759.89	42.07
+ GST 7.00/7.00% (S\$)	459.19	266.00	193.19	42.07
Nett Amount (S\$)	7,019.08	4,066.00	2,953.08	42.07
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 31/08/2021
 Date Inspected: 23/09/2021 Inspected At: Chew Goon Motor (AMK)
 17, AMK Autopoint
 Singapore 568047
 Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2021)
Parts:	M1-SUV	BMW X1 SDRIVE18I 1.5 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY5488T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE EMBLEM	Necessary	77.50 FL	*77.50 FL
2	1		*REAR BUMPER	Bent	990.00 FL	*990.00 FL
3	1		*REAR BUMPER CLIPS (14 PCS)	Necessary	54.60 FL	*30.00 FL
4	2		*REAR BUMPER BRACKETS	No such part	350.00 FL	*- FL
5	1		*REAR BUMPER SPONGE	No such part	180.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	545.00 FL	*545.00 FL
7	1		*REAR BUMPER INNER CORE	No such part	194.00 FL	*- FL
8	2		*REAR BUMPER LOWER RETAINERS	Broken	250.00 FL	*250.00 FL
9	1		*REAR BUMPER CENTER COVER	Broken	250.00 FL	*126.50 FL
10	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	100.00 FL	*100.00 FL
11	1		*REAR BUMPER LOWER DIFFUSER COVER	Dented	238.00 FL	*189.40 FL
12	1		*REAR BUMPER LOWER DIFFUSER COVER CENTER GARNISH COVER	Broken	125.00 FL	*125.00 FL
13	1		*REAR BUMPER TOW POINT COVER	Cut	40.00 FL	*40.00 FL
14	1		*REAR BUMPER INNER BOOT SENSOR STRIP	Dented	50.00 FL	*50.00 FL
15	1		*REAR BUMPER INNER BOOT SENSOR ANTENNA	Torn	55.00 FL	*55.00 FL
16	1		*REAR BUMPER INNER BOOT SENSOR MODULE	Broken	532.00 FL	*532.00 FL
17	1		*REAR BUMPER INNER BOOT SENSOR MODULE HOUSING	Cut	51.00 FL	*51.00 FL
18	1		*REAR EXHAUST SILENCER HEAT SHIELD	Dented	340.00 FL	*105.00 FL
19	1		*TAILGATE BADGE TURBO	Necessary	80.00 FS	*80.00 FS
20	1		*TAILGATE STICKER	Necessary	120.00 FS	*50.00 FS
21	1		*TAILGATE BADGE X1 (BLACK EDITION)	Necessary	120.00 FS	*58.35 FS
22	1		*REAR BUMPER TOP CARBON STICKER	Necessary	180.00 FS	*50.00 FS
23	1		*REAR BUMPER TOP PERFORMANCE STICKER	Necessary	150.00 FS	*150.00 FS
24	1		*REAR BUMPER REVERSE SENSOR	Broken	250.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,322.10	3,904.75
- List Item Discount on L Items 10.00/10.00% (\$\$)	442.21	326.64
Total Parts (\$\$)	4,879.89	3,578.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT ELECTRICAL CHECK ,REPLACE REVERSE SENSORS ,REPGORGRAM SYSTEM	New	120.00	60.00
2	TO REPAIR REAR EXHAUST SILENCER & TIP	New	60.00	0.00
3	LABOUR CHARGE-PANEL BEATING ,REPAIRING REAR TAILGATE ,END PANEL AND PARTS REPLACEMENT	New	700.00	500.00
4	TO SPRAY PAINT AFFECTED AREAS (2K-3TONE)	New	800.00	600.00
Gross Labour Cost (S\$)			1,680.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >