

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21009120/KPA3Q2**Date:** 02/02/2023**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** SKW2738R **Insured Vehicle No :** SMP9979D

Date of Loss: 27/08/2021 Nature of Claim: TP Claim No: 5548534892SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SKW2738R**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A) Engine No: 1ZR533955

Reg. Date: 23/10/2015 (Man. Year: 2015) Chassis No: MR053REH104539883

Colour: Metallic Silver Odometer: 88046 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                                       | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                                       | 7,512.72          | 5,703.05          | 1,809.67          | 24.09         |
| Miscellaneous Items                                         | 0.00              | 0.00              | 0.00              |               |
| Labour                                                      | 1,880.00          | 1,440.00          | 440.00            | 23.40         |
| Paintwork Labour                                            | 0.00              | 0.00              | 0.00              |               |
| Towing                                                      | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>                         | <b>9,392.72</b>   | <b>7,143.05</b>   | <b>2,249.67</b>   | <b>23.95</b>  |
| <b>Approved Total (Overridden) (S\$)</b>                    |                   | <b>5,700.00</b>   |                   |               |
| <b>(S\$)</b>                                                | 9,392.72          | 5,700.00          | 3,692.72          | 39.31         |
| <b>+ GST 7.00/7.00% (S\$)</b>                               | 657.49            | 399.00            | 258.49            | 39.31         |
| <b>Nett Amount (S\$)</b>                                    | <b>10,050.21</b>  | <b>6,099.00</b>   | <b>3,951.21</b>   | <b>39.31</b>  |
| <b>+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)</b> |                   | 428.00            |                   |               |
| <b>(S\$)</b>                                                |                   | 6,527.00          |                   |               |
| <b>Liabe Amount (50.00%) (S\$)</b>                          |                   | <b>3,263.50</b>   |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                               |                   | 29.00             |                   |               |
| <b>Nett Liability (S\$)</b>                                 |                   | <b>3,292.50</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>                          |                   | <b>3,250.00</b>   |                   |               |

**INSPECTION**

Date of Assignment: 31/08/2021

Date Inspected: 31/08/2021 Inspected At: Chew Goon Motor (AMK)  
Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 4.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## Recommended Parts

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                          |                 |                 |
|--------------------------|-----------------|-----------------|
| <b>Total Parts (S\$)</b> | <b>7,512.72</b> | <b>5,703.05</b> |
|--------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                     | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                 |          |                 |                 |
| 1                               | TO DISMANTLE /TRANSFER DOOR FITTINGS /ANCILLARY /ACCESSORIES                                    | New      | 150.00          | 60.00           |
| 2                               | TO CONDUCT ELECTRICAL CHECK ,FOCUS HEADLAMP                                                     | New      | 30.00           | 20.00           |
| 3                               | TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL        | New      | 100.00          | 60.00           |
| 4                               | LABOUR CHARGE-PANEL BEATING ,REPAIRING OF FENDER INNER PANEL ,DOOR PILLAR AND PARTS REPLACEMENT | New      | 600.00          | 500.00          |
| 5                               | TO RESPRAY AFFECTED AREAS                                                                       | New      | 1,000.00        | 800.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                 |          | <b>1,880.00</b> | <b>1,440.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >