

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 5757D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	TO REPAIR SEE LABOUR	976.47	-
1	BOOTLID WEATHERSTRIP	TWISTED	298.30	298.30
1	BOOTLID REAR LOGO	SERVICEABLE	105.00	-
1	BOOTLID 'LEXUS' EMBLEM	NOT NECESSARY	82.00	-
1	BOOTLID 'ES 300' EMBLEM	NOT NECESSARY	80.00	-
1	BOOTLID INNER LOCK	SERVICEABLE	509.10	-
1	REAR BUMPER	DEFORMED / TORN	1,015.90	1,015.90
1	REAR BUMPER LOWER CENTRE GARNISH	CRACKED	345.50	345.50
2	REAR BUMPER REFLECTORS @\$65.00	NOT NECESSARY	130.00	-
1	REAR BUMPER BEAM	DENTED	685.20	685.20
1	REAR BUMPER SPONGE	TORN	188.90	188.90
2	REAR BUMPER PDC SENSOR @\$477.10	SHORTED	954.20	954.20
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	715.50	-
1	REAR END PANEL TOP GARNISH	TWISTED	408.80	408.80
	LESS 10% DISCOUNT		-	-394.68
			6,544.87	3,552.12
	LABOUR			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REAR PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY.		120.00	80.00
	TO RESET & REPROGRAMME SYSTEM.		180.00	100.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	80.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID AND REAR END PANEL.		980.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,280.00	850.00
			2,770.00	1,700.00
	GRAND TOTAL		9,314.87	5,252.12

Report Ref No. CS/TP21009122/Uqf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,200.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/TP21009122/Uqf3e2

CHUA KANG SENG
Licensed Appraiser