

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 5412R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	118.00	-
1	TAILGATE	TO REPAIR SEE LABOUR	945.20	-
1	TAILGATE "STREAM" EMBLEM	NECESSARY	48.50	38.20
1	TAILGATE INNER LOCK	NOT NECESSARY	195.20	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	168.30	-
1	REAR BUMPER	DEFORMED / WARPED	698.30	665.40
2	REAR BUMPER SIDE RETAINERS @\$25.00	NECESSARY	50.00	50.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	39.00
1	SET REAR BUMPER REVERSE SENSOR	SHORTED	250.00	250.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	326.60	-
1	REAR WINDSCREEN SEALANT	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN INNER SEAL	NOT NECESSARY	50.00	-
	LESS 20% DISCOUNT		-	-208.52
			2,950.10	834.08
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	60.00
	TO DISMANTLE & REFIX TAILGATE MECHANISM.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR END PANEL.		800.00	450.00
	TO PUTTY & SPRAY PAINTING.		900.00	600.00
			2,300.00	1,180.00
	GRAND TOTAL		5,250.10	2,014.08

Report Ref No. CS/AGI21009124/Utf3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI21009124/Utf3n2

CHUA KANG SENG

**Licensed Appraiser**