



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 8877K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED / WARPED	1,887.00	1,476.68
1	FRONT BUMPER LOWER LIP (CONSISTENT)	NOT FITTED	336.00	-
2	FRONT BUMPER SIDE RETAINERS @\$75.50 (CONSISTENT)	NOT NECESSARY	151.00	-
2	FRONT BUMPER SIDE CHROME MOULDING @\$125.00 (CONSISTENT)	NECESSARY	250.00	232.00
1	FRONT BUMPER FOG LAMPS N/S (CONSISTENT)	NOT NECESSARY	290.00	-
1	FRONT BUMPER FOG LAMP COVER N/S (CONSISTENT)	NOT NECESSARY	142.00	-
1	FRONT HEADLAMPS N/S (CONSISTENT)	CRACKED	3,617.00	1,845.21
1	FRONT FENDER N/S (CONSISTENT)	TO REPAIR SEE LABOUR	1,085.00	-
1	FRONT FENDER EMBLEM N/S (CONSISTENT)	NECESSARY	68.00	68.00
1	FRONT FENDER CHROME MOULDING N/S (CONSISTENT)	NECESSARY	75.00	75.00
1	FRONT FENDER INNER SHIELD UPPER N/S (CONSISTENT)	NOT NECESSARY	207.00	-
1	FRONT FENDER INNER SHIELD LOWER N/S (CONSISTENT)	NOT NECESSARY	163.00	-
1	FRONT SHOCK ABSORBER N/S (CONSISTENT)	NOT NECESSARY	1,074.00	-
1	FRONT KNUCKLE ARM N/S (CONSISTENT)	NOT NECESSARY	1,476.00	-
1	FRONT LOWER ARM N/S (CONSISTENT)	NOT NECESSARY	972.00	-
1	FRONT STAY ARM N/S (CONSISTENT)	NOT NECESSARY	706.00	-
1	FRONT WHEEL HUB BEARING N/S (CONSISTENT)	NOT NECESSARY	654.00	-
	LESS 10% DISCOUNT		-1,315.30	-369.69
			11,837.70	3,327.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT FENDER INNER SHIELD CLIP (SN) (CONSISTENT)	NOT NECESSARY	65.00	-
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	65.00	50.00
1	FRONT TYRE (SN) (CONSISTENT)	SERVICEABLE	400.00	-
1	FRONT SPORT RIM (SN) (CONSISTENT)	CUT	1,800.00	680.00
			2,330.00	730.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.		120.00	20.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.	NOT NECESSARY	500.00	-
	TO CONDUCT WHEEL ALIGNMENT.		180.00	60.00
	TO APPLY UNDERCOATING.	NOT NECESSARY	150.00	-
	TO RESPRAY PAINTING ON AFFECTED AREAS.		1,000.00	500.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER N/S.		1,000.00	380.00
			2,950.00	960.00
	<b>GRAND TOTAL</b>		<b>17,117.70</b>	<b>5,017.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,000.00</b>

Report Ref No. CS/ASM21009126/Uqce2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.