

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC21009127/Guf3e2	
	300 BEACH ROAD #17-04/07 THE CO	) NCOURSESINGAPORE 199555	I	Date:	26/10/2021	
			(	Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YM 7687H	Veh. Inspected		GBK 821R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/21/21/VC05/024907	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		31/08/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTFHT02P300249761	Colour		SILVER	
	Odometer	39493 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15	BRIDGESTONE		6 mm	
	L/H Front Tyre	195 R15	BRIDGESTONE		6 mm	
	R/H Rear Tyre	195 R15	BRIDGESTONE		6 mm	
	L/H Rear Tyre	195 R15	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	22/08/2021	Inspection Date	<b>;</b>	31/08/2021	
	Survey held at	KUO LI AUTO WORKSHOP				
		BLK 5035 AMK INDUSTRIAL PARK 2 #01-363 SINGAPORE 569536				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				