

SLA 2017S 2016 Feb.

2021 August.

Toyota Fielder 1496 cc.

TP AXA.

Xiao Tony

NRE1618001067.

Front Bumper.	Deformed	563.10.	✓
Front Bumper Clips.	nee	30(SN)	✓
Front Bumper Side Holder RH.	Damaged	38.40.	—
Headlamps RH.	Cracked	1029.70.	—
Front RH Fender	Dented	480.30.	—
Front RH Fender Inner Shield.	Deformed	204.10	—
Front RH Fender Inner Shield Clips.	nee	30(SN)	—
Front RH Wheel Reim.	Cut	680(SN) 500(SN)	—
Front RH Tyre.	not nee	280(SN)	X.
Front RH Shock Absorber.	not nee	575.90	X
Front RH lower Arm.		489.50	X
Front RH Knuckle Arm.		497.90	X
Front RH Wheel Hub c/w Bearings.	Damaged	237.40	✓

SLA 2017S

Panel Beating

~~600~~ 450

Spray Painting.

~~600~~ 400

Wiring.

~~50~~ 30

To spray buff coat.

~~100~~ 30

To dismantle undercarriage -

~~280~~ 100

To perform wheel alignment.

~~180~~ 80

List 2553

Labour: 1040

less 25%: 1914.75

total: 3564.75

S.N: 510

A/S: 2.8K ✓

TOTAL ESTIMATE: \$6,916.30

04 Days.

2.8K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: