

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 5984D

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-----------------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT WINDSCREEN GLASS (N) | CRACKED | 987.00 | 450.00 |
| 1 | FRONT WINDSCREEN GLASS OUTER MOULDING (N) | CUT | 137.00 | 60.00 |
| 1 | FRONT WINDSCREEN GLASS DAMPER (N) | NOT NECESSARY | 60.00 | - |
| 20 | ROOF MOULDING CLIPS @\$5.50 (N) | NOT NECESSARY | 110.00 | - |
| 1 | O/S TAIL LAMP ASSY (N) (CRACKED) | NOT CONSISTENT WITH THE IMPACT | 332.00 | - |
| 8 | REAR BUMPER CLIPS @\$3.50 (N) | NOT NECESSARY | 28.00 | - |
| | COST PLUS 20% | | 330.80 | 102.00 |
| | | | 1,984.80 | 612.00 |
| | SPECIAL NETT ITEMS | | | |
| 1 | FRONT WINDSCREEN GLASS SEALANT (SN) | NECESSARY | 45.00 | 40.00 |
| 1 | FRONT WINDSCREEN GLASS ERP BRACKET STICKER (SN) | NECESSARY | 12.00 | 12.00 |
| 1 | FRONT WINDSCREEN GLASS SOLAR FILM (SN) | NOT NECESSARY | 350.00 | - |
| 1 | SET BODY STICKER (SN) (WAIVE REFER TO SPRAY PAINT) | | 2,400.00 | - |
| | | | 2,807.00 | 52.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE & REFIX FRONT WINDSCREEN GLASS & NECESSARY PARTS. | | 150.00 | 120.00 |
| | TO REMOVE & REFIX ROOF MOULDING, UPHOLSTERY, LINING, GARNISH, REAR N/S DOOR TRIM BOARD COVER, FRONT BONNET, INSULATOR & NECESSARY PARTS, TO ENABLE REPAIR ROOF PANEL, DOOR PILLAR, REAR N/S DOOR, FRONT BONNET & NECESSARY PARTS. | | 280.00 | 150.00 |
| | TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM. | NOT NECESSARY | 50.00 | - |
| | LABOUR CHARGE TO REMOVE & CUT OUT NECESSARY PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT ROOF PANEL, DOOR PILLAR PANEL, REAR BUMPER, REAR N/S DOOR, FRONT BONNET & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS. | | 900.00 | 800.00 |
| | TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS. | | 1,500.00 | 1,400.00 |

Report Ref No. CS/MSG21009133/Utf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-----------|-------------------------------|-------------------|
| | LABOUR CHARGE TO REMOVE & REFIX BODY STICKER & NECESSARY. | | 350.00 | 200.00 |
| | | | 3,230.00 | 2,670.00 |
| | GRAND TOTAL | | 8,021.80 | 3,334.00 |
| | | | | |
| | RECOMMENDED COST OF REPAIRS | | | 3.334.00 |

Report Ref No. CS/MSG21009133/Utf3e2

CHUA KANG SENG

Licensed Appraiser