

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	MSIG INSURANCE	(SINGAPORE) PTE LTD		Ref:	CS/MSG21009133/Utf3e2	
	4 SHENTON WAY SINGAPORE 0688	#21-01,SGX CENTRE 2 07		Date:	23/09/2021	
				Code:	MSG	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	ł	SJA 5984D	
	Policy No.	B 300445396 CAR	Coverage (\$)		0.00	
	Claim No.	261912 CAR	Excess (\$)		0.00	
	Assign From	LIM ZI LIANG	Assign Date		31/08/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI LANCER GLS (A)	c.c		1499	
	Engine No.	HIDDEN	Year of Reg.		2007	
	Chassis No.	JMYSRCY2A8U004458	Colour		GREY	
	Odometer	227897 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	PIRELLI		6 mm	
	L/H Front Tyre	205/55 R16	PIRELLI		6 mm	
	R/H Rear Tyre	205/55 R16	PIRELLI		6 mm	
	L/H Rear Tyre	205/55 R16	PIRELLI		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT WINDSCREEN CRACKED, ROOFTOP, FRONT, N/S BODY, REAR, O/S BODY. THE CAUSE OF DAMAGE DUE TO CONCRETE DEBRIS.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	27/08/2021	Inspection Dat	e	31/08/2021	
	Survey held at	rvey held at HUP MOTOR TRADING & SERVICE				
		BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		7 Worki	ng Days	