

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009134/AVCE2

Date: 20/12/2021

REFERENCE

Insured/Claimant: MANKUDE BHASKER RAO RAVI KIRAN
Date of Loss: 25/08/2021

Policy No: 7210042163
Nature of Claim: OD Claim No: 5666732467SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA3118D**
Make & Model: AUDI Q7, 2.0 TFSI QU (A) Engine No: CYR103337
Reg. Date: 29/04/2021 (Man. Year: 2020) Chassis No: WAUZZZ4M0MD008609
Colour: Blue Odometer: 3220 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$300,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55 R19 Rear Tyre Size: 255/55 R19
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	77,806.00	40,227.92	37,578.08	48.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	36,574.00	23,324.00	13,250.00	36.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	114,380.00	63,551.92	50,828.08	44.44
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	113,880.00	63,051.92	50,828.08	44.63
+ GST 7.00/7.00% (S\$)	7,971.60	4,413.63	3,557.97	44.63
Nett Amount (S\$)	121,851.60	67,465.55	54,386.05	44.63

INSPECTION

Date of Assignment: 31/08/2021

Date Inspected: 30/08/2021 Inspected At:

24 Benoi Sector

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 28.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,724.00 FS	*2,179.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	696.00 FS	*- FS
3	1		*FRONT TOWING EYE COVER	Not Necessary	39.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE - LH	Deformed	67.00 FS	*52.96 FS
5	1		*FRONT BUMPER COVER CAP - LH	Not Necessary	36.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTER	Cracked	277.00 FS	*221.20 FS
7	6		*FRONT BUMPER LOCKING CLIP	Not Necessary	24.00 FS	*- FS
8	1		*FRONT BUMPER GRILLE	Deformed	206.00 FS	*164.40 FS
9	1		*FRONT BUMPER SILVER UNDERRUN BAR	Deformed	583.00 FS	*466.40 FS
10	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Cracked	210.00 FS	*167.60 FS
11	1		*FRONT BUMPER SPOILER - LH / RH	N/S Deformed	422.00 FS	*168.80 FS
12	1		*FRONT BUMPER SPOILER - OUTER LH / RH	N/S Deformed	88.00 FS	*34.72 FS
13	1		*FRONT BUMPER TRIM - LH / RH	N/S Damaged	26.00 FS	*9.68 FS
14	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	N/S Cut	204.00 FS	*81.60 FS
15	1		*FRONT BUMPER AIR GUIDE GRILLE END CAP - LH / RH	N/S Deformed	96.00 FS	*38.16 FS
16	2		*AIR GUIDE GRILLE INSERT - LH	Deformed	102.00 FS	*41.20 FS
17	1		*FRONT RADIATOR GRILLE	Cracked	2,473.00 FS	*1,978.40 FS
18	1		*FRONT RADIATOR INNER COVER	Not Necessary	72.00 FS	*- FS
19	1		*FRONT CAMERA COVER	Not Necessary	13.00 FS	*- FS
20	2		*FRONT BUMPER SPOILER - INNER LH / RH	Not Necessary	118.00 FS	*- FS
21	1		*FRONT BUMPER CARRIER	Dented	964.00 FS	*771.20 FS
22	1		*FRONT BUMPER GUIDE SECTION - LH	Cracked	44.00 FS	*34.88 FS
23	1		*FRONT BUMPER TOP COVER	Not Necessary	131.00 FS	*- FS
24	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
25	1		*AIR-CONDITIONER STICKER	Not Necessary	8.00 FS	*- FS
26	2		*HORN - LH / RH	Not Necessary	452.00 FS	*- FS
27	2		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
28	4		*FRONT PARKING AID SENSOR SEAL	Not Necessary	14.00 FS	*- FS
29	1		*FRONT FENDER - LH / RH	N/S Repair / O/S Dented	3,240.00 FS	*1,296.00 FS
30	1		*FRONT FENDER ATTACHMENT PART	Not Necessary	117.00 FS	*- FS
31	1		*FRONT FENDER BRACE - LH	Not Necessary	101.00 FS	*- FS
32	1		*FRONT FENDER BRACKET - LH	Not Necessary	65.00 FS	*- FS
33	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	33.00 FS	*- FS
34	1		*WHEEL HOUSING LINER - FRONT LH	Not Necessary	240.00 FS	*- FS
35	1		*WHEEL HOUSING LINER - REAR LH	Not Necessary	240.00 FS	*- FS
36	1		*FRONT BONNET	Repair	6,672.00 FS	*- FS
37	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	224.00 FS	*- FS
38	1		*FRONT BONNET IMPACT PROTECTION	Not Necessary	107.00 FS	*- FS
39	1		*FRONT BONNET STRIKER - LH	Not Necessary	117.00 FS	*- FS
40	1		*FRONT BONNET LOCK WITH MICRO-SWITCH	Not Necessary	213.00 FS	*- FS
41	1		*FRONT HEADLIGHT MOUNTING - LH / RH	N/S Cracked	236.00 FS	*94.40 FS
42	1		*FRONT HEADLIGHT	N/S Cracked	17,248.00 FS	*6,924.00 FS
43	1		*FRONT HEADLIGHT HOSE - LH	Not Necessary	39.00 FS	*- FS
44	1		*FRONT HEADLIGHT LIFT CYLINDER - LH	Cracked	198.00 FS	*158.40 FS
45	1		*FRONT HEADLIGHT WASHER HOSE	Not Necessary	121.00 FS	*- FS
46	6		*FRONT BUMPER AIR GUIDE - LH / RH / UPPER / LOWER	Not Necessary	200.00 FS	*- FS
47	1		*FRONT AIR SENSOR BRACKET	Necessary	5.00 FS	*3.36 FS
48	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,112.00 FS	*889.60 FS
49	1		*FRONT DOOR - RH	Dented	5,087.00 FS	*4,069.60 FS
50	1		*FRONT DOOR SEAL	Necessary	253.00 FS	*202.00 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*FRONT DOOR BONDING AGENT	Not Necessary	49.00 FS	*- FS
52	1		*FRONT DOOR CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
53	1		*FRONT DOOR APPLICATOR	Not Necessary	8.00 FS	*- FS
54	8		*FRONT DOOR GROMMET	Not Necessary	21.00 FS	*- FS
55	1		*FRONT DOOR ATTACHMENT PART	Not Necessary	352.00 FS	*- FS
56	1		*FRONT DOOR CATCH - RH	Not Necessary	128.00 FS	*- FS
57	1		*FRONT DOOR COVER - RH	Necessary	858.00 FS	*686.40 FS
58	1		*TYRE PRESSURE STICKER	Not Necessary	42.00 FS	*- FS
59	1		*REAR DOOR COVER	Not Necessary	785.00 FS	*- FS
60	2		*WHEEL ARCH DOOR - LH / RH	Necessary	382.00 FS	*304.80 FS
61	1		*REAR BUMPER - UPPER	Deformed	1,362.00 FS	*1,089.60 FS
62	1		*REAR BUMPER - LOWER	Torn	1,841.00 FS	*1,472.80 FS
63	1		*REAR BUMPER FIXING PARTS	Not Necessary	439.00 FS	*- FS
64	1		*REAR BUMPER SPOILER	Torn	1,259.00 FS	*1,007.20 FS
65	1		*REAR BUMPER CARRIER	Not Necessary	1,417.00 FS	*- FS
66	1		*REAR BUMPER SEAL - LH / RH	Not Necessary	14.00 FS	*- FS
67	1		*REAR BUMPER HOLDING STRAP	Not Necessary	182.00 FS	*- FS
68	1		*REAR BUMPER GUIDE SECTION - CENTER	Not Necessary	142.00 FS	*- FS
69	1		*REAR BUMPER GUIDE SECTION - LH	Cracked	63.00 FS	*50.32 FS
70	1		*REAR TAIL LIGHT BULB - LH	Not Necessary	359.00 FS	*- FS
71	2		*REAR WHEEL COVER - LH / RH	Necessary	730.00 FS	*584.00 FS
72	1		*REAR QUARTER SIDE FENDER - LH	Dented	7,217.00 FS	*5,773.60 FS
73	1		*REAR QUARTER GLASS - LH	Necessary	946.00 FS	*756.80 FS
74	1		*ALUMINIUM POWDER	Necessary	573.00 FS	*458.40 FS
75	1		*HARDENER	Necessary	210.00 FS	*168.00 FS
76	1		*ALUMINIUM PRIMER	Necessary	212.00 FS	*169.60 FS
77	1		*CLEANING BLOCK	Not Necessary	77.00 FS	*- FS
78	1		*EPOXY ADHESIVE	Necessary	113.00 FS	*90.40 FS
79	1		*STATIC MIXER	Necessary	8.00 FS	*5.84 FS
80	1		*ALUMINIUM RIM (4PCS)	FrontN/S,FrontO/S,RearN/S Cut	8,456.00 FS	*5,349.60 FS
81	1		*REAR WHEEL SPOILER - LH	Not Necessary	36.00 FS	*- FS
82	1		*REAR SILL TRIM STRIP - LH	Not Necessary	165.00 FS	*- FS
83	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	320.00 FS	*- FS
84	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
85	1		*GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
86	1		*ARCRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
87	1		*CRAVITY WAX	Necessary	140.00 FS	*140.00 FS
88	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
89	1		*SUNDRIES	Necessary	500.00 FS	*81.28 FS
90	1		*FRONT BUMPER REINFORCEMENT FOAM	Cracked	171.00 FS	*136.80 FS
91	1		*REAR FENDER VENT TRIM-LH (Supplementary)	Cracked	73.00 FS	*57.92 FS
92	1		*COUNTERSUNK RIVET (Supplementary)	Necessary	105.00 FS	*84.00 FS
93	1		*SILL PANEL SEAL-LH (Supplementary)	Necessary	253.00 FS	*202.00 FS
94	1		*FRONT NOISE INSULATION (Supplementary)	Torn	636.00 FS	*508.80 FS
95	1		*RADIATOR LOUVRE (Supplementary)	Cracked	603.00 FS	*482.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 77,806.00 40,227.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	900.00	300.00
3	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	450.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS, RHS FRONT DOOR AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,400.00	1,800.00
5	TO RESPRAY FRONT BUMPER, BOTH FRONT BUMPER LOWER SPOILERS, BONNET, BOTH FRONT FENDERS, RHS FRONT DOOR, RHS REAR DOOR, LHS REAR DOOR, TWO DOOR COVERS AND BOTH FRONT & REAR WHEEL ARCH TRIMS	New	9,000.00	5,150.00
6	TO REMOVE AND REINSTALL REAR PARKING AID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
7	TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	300.00
8	TO INSTALL SOLAR FILM FOR LHS SIDE 1/4 GLASS	New	400.00	400.00
9	TO CARRY OUT WATER SEEPAGE TEST ON 1/4 GLASS	New	200.00	150.00
10	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	1,400.00
11	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
12	TO SET UP AND PLACE VEHICLE IN ALUMINIUM BAY	New	1,800.00	1,800.00
13	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS	New	6,300.00	4,800.00
14	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, LHS FENDER, LHS SILL PANEL, DRAIN CHANNEL, ROOF CHANNEL, DOOR ENTRANCE AND REAR END PANELLING	New	6,500.00	3,300.00
15	TO CARRY OUT ALUMINIUM PRIMER WORKS	New	900.00	900.00
16	TO RENEW ALL RIMS AND CARRY OUT WHEEL ALIGNMENT	New	400.00	400.00
17	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			36,574.00	23,324.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >