

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009136/KPS3Q2
Date: 06/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210045271
Claimant Vehicle No :	SKS566D	Insured Vehicle No :	GBL2976J
Date of Loss:	30/08/2021	Nature of Claim:	TP
		Claim No:	8719849299SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS566D	Engine No:	1ZRY135766
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH104523271
Reg. Date:	25/03/2015 (Man. Year: 2014)	Odometer:	117985 km
Colour:	Metallic Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 3 mm	Rear Left Side:	Goodyear 3 mm
Front Right Side:	Goodyear 3 mm	Rear Right Side:	Goodyear 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,904.75	4,084.40	820.35	16.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,330.00	1,370.00	50.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,604.75	5,414.40	2,190.35	28.80
Approved Total (Overridden) (S\$)		4,300.00		

(S\$)	7,604.75	4,300.00	3,304.75	43.46
+ GST 7.00/7.00% (S\$)	532.33	301.00	231.33	43.46
Nett Amount (S\$)	8,137.08	4,601.00	3,536.08	43.46
+ Car Rental (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,903.00		

INSPECTION

Date of Assignment: 31/08/2021

Date Inspected: 31/08/2021

Estimated Period of Repair: 5.0 days

Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	755.00 FL	*755.00 FL
2	1		*REAR BOOTLID COROLLA EMBLEM	Necessary	70.00 FL	*70.00 FL
3	1		*REAR BOOTLID ALTIS EMBLEM	Necessary	70.00 FL	*70.00 FL
4	1		*REAR BOOTLID LOGO EMBLEM	Necessary	80.00 FL	*80.00 FL
5	1		*REAR BOOTLID CHROME MOULDING	Cracked	233.00 FL	*233.00 FL
6	1		*REAR BOOTLID WEATHERSTRIP (50%)	Distorted / Dented	138.75 FS	*92.50 FS
7	1		*REAR BOOTLID INNER LOCK	Dented	385.00 FL	*385.00 FL
8	1		*REAR BOOTLID INNER TRIM	Serviceable	502.00 FL	*- FL
9	1		*REAR BOOTLID LAMP LH	Cracked	355.00 FL	*355.00 FL
10	1		*REAR BOOTLID LAMP RH	Mtg Cracked	355.00 FL	*355.00 FL
11	1		*REAR TAIL LAMP LH	Mtg Cracked	395.00 FL	*380.10 FL
12	1		*REAR TAIL LAMP RH	Dented / Cut	395.00 FL	*380.10 FL
13	1		*REAR BUMPER	Buckled	486.00 FL	*486.00 FL
14	1		*REAR BUMPER SIDE BRACKET LH	Distorted	110.00 FL	*110.00 FL
15	1		*REAR BUMPER SIDE BRACKET RH	Distorted	110.00 FL	*110.00 FL
16	1		*REAR BUMPER REFLECTOR LH	Serviceable	60.00 FL	*- FL
17	1		*REAR BUMPER REFLECTOR RH	Cracked	60.00 FL	*60.00 FL
18	1		*REAR END PANEL	Bent	590.00 FL	*590.00 FL
19	1		*REAR END PANEL UPPER COVER	Mtg Cracked	240.00 FL	*240.00 FL
20	1		*REAR SPARE TYRE UPPER BOARD	Serviceable	267.00 FL	*- FL
21	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
22	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT	Bent	250.00 FL	*250.00 FL
24	1		*REAR BUMPER REVERSE SENSOR	Dented / Shorted	300.00 FS	*200.00 FS
25	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
26	1		*REAR END PANEL UPPER COVER CLIPS	Necessary	30.00 FS	*30.00 FS
27	1		*REAR END PANEL JOINT SEALANT	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,346.75	5,311.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,442.00	1,227.30
Total Parts (\$\$)	4,904.75	4,084.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	1,200.00	600.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID ,REAR BUMPER,REAR END PANEL ,REAR FENDER LH ,REAR FENDER RH & ETC	New	1,200.00	600.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	120.00	50.00
4	TO TUFF KOTE & UNDERSEAL MATERIALS	New	100.00	60.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
Gross Labour Cost (S\$)			2,700.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >