

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009140/T1VCN2**Date:** 16/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00057522101

Claimant Vehicle No : GBA5870T **Insured Vehicle No :** YN383A

Date of Loss: 30/08/2021 Nature of Claim: TP Claim No: SNM21D204866/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA5870T**

Make & Model: SUZUKI EVERY, 660cc PA (DA64V) (M) Engine No: K6A7120999

Reg. Date: 30/08/2007 (Man. Year: 2007) Chassis No: DA64V201537

Colour: White Odometer: 238268 km

Engine Capacity: 658 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 155R12 Rear Tyre Size: 155R12

Front Left Side: CST 6 mm Rear Left Side: CST 6 mm

Front Right Side: CST 6 mm Rear Right Side: CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,055.20	3,010.10	2,045.10	40.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,530.00	1,230.00	44.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,815.20	4,540.10	3,275.10	41.91
Approved Total (Overridden) (\$\$)		2,500.00		
Nett Amount (\$\$)	7,815.20	2,500.00	5,315.20	68.01

INSPECTION

Date of Assignment: 31/08/2021

Date Inspected: 31/08/2021 Inspected At: Carsmith Private Limited (HQ)
13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE
Singapore 417807

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Sep 2021)	
Parts:	N/A	SUZUKI EVERY 660cc PA (DA64V) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA5870T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,018.60 FL	*1,018.60 FL
2	1		*TAILGATE INNER TRIM BOARD	Not Necessary	210.40 FL	*- FL
3	1		*TAILGATE INNER TRIM BOARD CLIPS (SET)	Not Necessary	25.00 FL	*- FL
4	1		*TAILGATE WEATHERSTRIP	Not Necessary	175.40 FL	*- FL
5	1		*TAILGATE INNER LOCK	Bent	125.80 FL	*125.80 FL
6	1		*TAILGATE WINDSCREEN GLASS	Broken	826.30 FL	*826.30 FL
7	1		*TAILGATE LOGO S	Necessary	78.20 FL	*78.20 FL
8	1		*TAILLAMP ASSY RH	Cracked	386.70 FL	*386.70 FL
9	1		*REAR BUMPER	Deformed	580.40 FL	*580.40 FL
10	2		*REAR BUMPER BRACKET	Not Necessary	136.40 FL	*- FL
11	1		*REAR BUMPER CLIPS (SET)	Necessary	35.00 FL	*30.00 FL
12	1		*REAR END PANEL	Repair	486.70 FL	*- FL
13	1		*REAR FLOOR PANEL	Not Necessary	1,102.40 FL	*- FL
14	1		*REAR TAILGATE INNER GLASS INNER SEAL/SPONGE TAP	Necessary	121.00 FS	*121.00 FS
15	1		*REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
16	1		*REAR TAILGATE STICKER (4 PAX)	Necessary	30.00 FS	*30.00 FS
17	1		*REAR TAILGATE STICKER (70KM/HX)	Necessary	30.00 FS	*30.00 FS
18	1		*REAR END PANEL SEALANT/JOINT	Not Necessary	80.00 FS	*- FS
19	1		*REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
20	1		*REAR NUMBER PLATE	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,833.30	3,467.00
- List Item Discount on L Items 15.00/15.00% (S\$)	778.10	456.90
Total Parts (S\$)	5,055.20	3,010.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,000.00	600.00
2	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,000.00	600.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
4	TO TRANSFER TAILGATE ATTACHMENT,TRIMS,GARNISH TO FACILITATE REPAIRS	New	120.00	60.00
5	TO REMOVE & INSTALL REAR TAILGATE GLASS TO FACILITATE REPAIRS	New	150.00	120.00
6	TO CONDUCT WATER SEEPAGE TEST	New	120.00	30.00
7	TO TRANSFER REAR COMPARTMENT TRIMS,GARNISH TO FACILITATE REPAIRS	New	120.00	60.00
8	TO RUST PROOF AFFECTED AREAS	New	200.00	30.00
Gross Labour Cost (\$)			2,760.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >