



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 7718L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DEFORMED	1,450.00	1,215.00
1	SET FRONT BUMPER CLIP	NECESSARY	40.00	40.00
1	FRONT BUMPE CHROME TRIM	CUT	250.00	98.00
1	FRONT BONNET	DENTED	1,850.00	1,850.00
1	N/S FRONT HEAD LAMP	CUT	1,485.00	1,250.00
1	N/S FRONT FENDER	DENTED	840.00	840.00
1	N/S FOG LAMP CHROME GARNISH	CRACKED	195.00	195.00
1	SET FRONT BUMPER SIDE RETAINER	NECESSARY	95.00	95.00
1	WHEEL BEARING	NOT NECESSARY	480.00	-
1	FRONT ABSORBER	NOT NECESSARY	685.00	-
	LESS 10% DISCOUNT		-	-558.30
			7,370.00	5,024.70
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	N/S SPORT RIM (SN)	CUT	950.00	500.00
			950.00	500.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE DAMAGED PARTS, PANEL BEAT, REPAIR.		900.00	600.00
	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREA.		900.00	800.00
	ANTI RUST.		80.00	50.00
	CHECK WHEEL ALIGNMENT.		150.00	80.00
	ELETRICAL WIRING CHECK.		80.00	30.00
	UNDERCARRIAGE.	NOT NECESSARY	120.00	-
			2,230.00	1,560.00
	<b>GRAND TOTAL</b>		<b>10,550.00</b>	<b>7,084.70</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,600.00</b>
---	--	--	-----------------

Report Ref No. CS/UOI21009144/Avf3e2

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**