

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009145/ABS3Q2
Date: 12/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SDJ9989M	Insured Vehicle No :	SLU2527G
Date of Loss:	30/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003693

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDJ9989M		
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Engine No:	3ZRB820968
Reg. Date:	17/08/2016 (Man. Year: 2016)	Chassis No:	ZSU600082767
Colour:	Maroon	Odometer:	53186 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,834.87	9,031.77	5,803.10	39.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,690.00	1,840.00	850.00	31.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,524.87	10,871.77	6,653.10	37.96
Approved Total (Overridden) (S\$)		8,700.00		

(S\$)	17,524.87	8,700.00	8,824.87	50.36
+ GST 7.00/7.00% (S\$)	1,226.74	609.00	617.74	50.36
Nett Amount (S\$)	18,751.61	9,309.00	9,442.61	50.36
+ Car Rental (8.0 x S\$120.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,276.45		
Global Sum Settlement (S\$)		10,200.00		

INSPECTION

Date of Assignment: 31/08/2021

Date Inspected: 03/09/2021

Inspected At: Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2021)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDJ9989M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,450.40 FL	*1,450.40 FL
2	2		*FRONT BUMPER SIDE HOLDER-LH& RH	Necessary	196.20 FL	*196.20 FL
3	1		*FRONT BUMPER LOWER GRILLE	Cracked	365.00 FL	*365.00 FL
4	1		*FRONT BUMPER LOWER GARNISH	Not Necessary	378.10 FL	*- FL
5	1		*FRONT BUMPER UNDERCOVER	Deformed	301.70 FL	*301.70 FL
6	1		*FRONT BUMPER CENTRE SPONGE	Cracked	172.00 FL	*172.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	490.60 FL	*- FL
8	1		*FRONT BUMPER CENTER BEAM	Bent	236.80 FL	*236.80 FL
9	1		*FRONT GRILLE	Cracked	536.10 FL	*536.10 FL
10	1		*HEAD LAMP -LH & RH	N/S Cracked	7,060.20 FL	*3,530.10 FL
11	1		*HEAD LAMP LOWER SPONGE -LH & RH	N/S Cracked	224.40 FL	*112.20 FL
12	1		*FRONT BRACE PANEL	Bent	226.10 FL	*226.10 FL
13	1		*FRONT SUPPORT PANEL	Repair	798.50 FL	*- FL
14	1		*FRONT SUPPORT PANEL TOP COVER	Not Necessary	280.40 FL	*- FL
15	1		*FRONT FENDER -LH	Buckled	1,090.50 FL	*1,090.50 FL
16	1		*BONNET	Dented	1,880.40 FL	*1,880.40 FL
17	1		*BONNET LOCK	Not Necessary	145.60 FL	*- FL
18	1		*BONNET OUTER MOULDING	Missing	295.40 FL	*295.40 FL
19	1		*AIR CON CONDENSER	Bent	1,447.80 FL	*1,447.80 FL
20	1		*AIR CON CONDENSER SIDE GUIDE	N/S Deformed	70.00 FL	*35.00 FL
21	1		*RADIATOR	Not Necessary	1,860.30 FL	*- FL
22	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
23	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
24	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
25	1		*SET FRONT BUMPER UNDERCOVER CLIPS	Necessary	25.00 FS	*25.00 FS
26	1		*SET FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
27	1		*SET FRONT SUPPORT PANEL TOP COVER CLIPS	Necessary	30.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*SET BONNET OUTER MOULDING CLIPS	Necessary	20.00 FS	*20.00 FS
29	1		*SET AIR CON CONDENSER SIDE GUIDE CLIPS	Necessary	20.00 FS	*10.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					19,711.50	12,000.70
- List Item Discount on L Items 25.00/25.00% (\$)					4,876.63	2,968.93
Total Parts (\$)					14,834.87	9,031.77
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT FRONT PORTION & RENEW ABOVE PARTS	New	1,200.00	800.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,200.00	950.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE CONDENSER & TOP UP AIRCON GAS	New	120.00	60.00
5	TO REMOVE RADIATOR & TO UP COOLANT	New	120.00	0.00
Gross Labour Cost (S\$)			2,690.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >