

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009148/KEA3Q2
Date: 14/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070030164
Claimant Vehicle No :	SJR338M	Insured Vehicle No :	GBE8233S
Date of Loss:	27/08/2021	Nature of Claim:	TP
		Claim No:	1841261683SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR338M		
Make & Model:	BMW 320I, 1.6 EFFICIENT DYNAMICS 2WD NAV HID (A)	Engine No:	A453J845N13B16A
Reg. Date:	27/04/2015 (Man. Year: 2014)	Chassis No:	WBA3J92060J642788
Colour:	Metallic Black	Odometer:	96113 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45Z R18	Rear Tyre Size:	225/45Z R18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,972.70	1,557.63	1,415.07	47.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	530.00	470.00	47.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,972.70	2,087.63	1,885.07	47.45
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		

Nett Liability (S\$)**2,207.63**INSPECTION

Date of Assignment: 31/08/2021

Date Inspected: 06/09/2021

Estimated Period of Repair: 2.0 days

Inspected At:

TROPICAL TECH AUTOMOBILE SERVICES
BLK 5032, ANG MO KIO AVENUE 3
#01-201
IND. PARK 2
SINGAPORE 569535**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	1,889.00 FL	*1,237.80 FL
2	2		*REAR BUMPER PARKTRONIC SENSOR (CENTRE)	Serviceable	490.00 FL	*- FL
3	4		*REAR BUMPER PARKTRONIC SENSOR SEAL RING	Necessary	60.00 FL	*60.00 FL
4	1		*REAR BUMPER TOWING COVER	Serviceable	81.00 FL	*- FL
5	1		*REAR BUMPER SIDE BRACKET (RH)	Repair	108.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	675.00 FL	*432.90 FL

F=Franchise part. L=ListItemDisc.

	Sub Total (\$\$)	3,303.00	1,730.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	330.30		173.07
	Total Parts (\$\$)	2,972.70	1,557.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPART PART ITEMS }	New	400.00	220.00
2	REMOVE AND REFIT REAR BUMPER ,REAR BUMPER PARKTRONIC SENSORS (CENTRE) ,REAR BUMPER PARKTRONIC SENSOR SEAL RINGS ,REAR BUMPER TOWING COVER ,REAR BUMPER SIDE BRACKET (RH) ,REAR BUMPER REINFORCEMENT }	New	0.00	0.00
3	DIAGNOSTIC AND RESET REAR BUMPER PARKTRONIC SENSOR FAULT ERROR BY HHT	New	100.00	60.00
4	PUTTY/PRIMER APPLICATION SPRAY PAINTING REAR BUMPER,REAR BUMPER PARKTRONIC SENSORS ,REAR BUMPER TOWING COVER	New	500.00	250.00
Gross Labour Cost (S\$)			1,000.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >