

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009149/UES3Q2
Date: 16/12/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0003221
Claimant Vehicle No :	SLH3201H	Insured Vehicle No :	FBR6022D
Date of Loss:	28/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003702

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH3201H	Engine No:	2AZL012622
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Chassis No:	ACR507133467
Reg. Date:	28/10/2016 (Man. Year: 2016)	Odometer:	78748 km
Colour:	White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,042.45	1,037.10	2,005.35	65.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	770.00	1,140.00	59.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,952.45	1,807.10	3,145.35	63.51
Approved Total (Overridden) (S\$)		1,400.00		

(S\$)	4,952.45	1,400.00	3,552.45	71.73
+ GST 7.00/7.00% (S\$)	346.67	98.00	248.67	71.73
Nett Amount (S\$)	5,299.12	1,498.00	3,801.12	71.73
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,719.45		

INSPECTION

Date of Assignment: 31/08/2021

Date Inspected: 22/09/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2021)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH3201H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,355.80 FL	*1,355.80 FL
2	6		*REAR BUMPER CLIPS	Necessary	27.00 FL	*27.00 FL
3	1		*REAR BUMPER REFLECTOR O/S	Not Necessary	328.00 FL	*- FL
4	1		*O/S REAR FENDER	Repair	855.00 FL	*- FL
5	1		*O/S REAR FENDER INNER COOLING	Not Necessary	95.00 FL	*- FL
6	6		*O/S REAR FENDER INNER COOLING CLIPS	Not Necessary	25.80 FL	*- FL
7	1		*O/S TYRE RIM	Serviceable	1,050.00 FL	*- FL
8	1		*O/S REAR FENDER 1/4 GLASS PRIMER	Not Necessary	40.00 FS	*- FS
9	1		*O/S REAR FENDER 1/4 GLASS INNER SEAL	Not Necessary	120.00 FS	*- FS
10	1		*O/S REAR FENDER 1/4 GLASS SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,976.60	1,382.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	934.15	345.70
Total Parts (\$\$)	3,042.45	1,037.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	700.00	300.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	50.00
4	TO TRANSFER OF TYRE ,RIM AND ON WHEEL BALANCING	New	50.00	0.00
5	TO UPHOLSTERY AND MAKE GOOD REPAIR TO CUSHION SEAT AND SEAT FRAME AND RECLINING MECHANISM	New	200.00	0.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	800.00	400.00
Gross Labour Cost (\$\$)			1,910.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >