



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4980D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	CUT	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	CUT	451.25	451.25
1	REAR BUMPER REINFORCEMENT	CUT	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET LH / RH @ \$138.10	DENTED (1PC ONLY)	276.20	138.10
1	REAR BUMPER LOWER CTR MOULDING	DISTORTED	155.00	155.00
1	REAR BUMPER REFLECTOR LAMP LH	SERVICEABLE	41.45	-
1	REAR BUMPER TOWING COVER	CUT	98.80	98.80
1	REAR BUMPER FOG LAMP	SERVICEABLE	201.50	-
1	BOOTLID	DEFORMED	2,480.40	2,480.40
1	BOOTLID HYUNDAI PLATE	NECESSARY	24.30	24.30
1	EMBLEM HYBRID	NECESSARY	24.30	24.30
1	EMBLEM - IONIQ	NECESSARY	31.30	31.30
1	ANTENNA ASSY SMARTKEY	SERVICEABLE	40.50	-
1	LICENCE LAMP	SERVICEABLE	85.30	-
	LESS 20% DISCOUNT		-957.30	-855.93
			3,829.20	3,423.72
<u>NETT ITEMS</u>				
1	REAR NUMBER PLATE + TRIM COVER (N)	CRACKED	55.00	55.00
1	BOOTLID COMFORT TEL NO STICKER (N)	NECESSARY	35.00	35.00
1	BOOTLID COMFORT LOGO STICKER (N)	NECESSARY	30.00	30.00
1	BOOTLID COMFORT APP STICKER (N)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (N)	CUT	180.00	180.00
	LESS 10% DISCOUNT		-	-33.00
			330.00	297.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00

Report Ref No. NS/INC21009150/Vvce2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL (SN)	TO REPAIR SEE LABOUR	175.00	
			225.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	WIRING CHARGE.		50.00	20.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
			1,530.00	1,250.00
GRAND TOTAL			5,914.20	5,020.72
RECOMMENDED COST OF REPAIRS (CONFIRMED)				5,020.72

Report Ref No. NS/INC21009150/Vvce2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.