



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1248K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	430.90	-
1	RADIATOR GRILLE	SCRATCHED	1,409.10	1,409.10
1	FRONT CENTRE MOULDING	SCRATCHED	368.50	368.50
1	HEAD LAMP LH	SCRATCHED	1,993.65	1,993.65
10	BUMPER CLIP	NECESSARY	22.00	22.00
1	FRONT NUMBER PLATE MOUNTING	SERVICEABLE	188.00	-
	LESS 20% DISCOUNT		-882.43	-758.65
			3,529.72	3,034.60
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	NUMBER PLATE W/HOLDER (SN)	SCRATCHED	55.00	55.00
			55.00	55.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER.		550.00	350.00
	SPRAY PAINT.		300.00	250.00
	CHECK LIGHTING.		60.00	30.00
			910.00	630.00
	<b>GRAND TOTAL</b>		<b>4,494.72</b>	<b>3,719.60</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>2,950.00</b>

Report Ref No. NS/INC21009151/Vvcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.