Our	Job Re	fNo :	305484305	COMFORTDELGRO				
Dat	е	:	02/09/21		ComfortDelGro Engineering Pte Ltd			
FIN	ALIZAT	ION FORM			59 L	oyang Drive Singapore 508969		
To	; _		LKK		Fax:			
Attr	Attn :		THEVAN					
Vel	nicle Reg	g No. : SHC	1248K			26/08/2021		
The	survey	and estimates of	the repairs of the above-me	ntioned vehicle	are as follows	S:-		
Z	The	repair job shall bi	II to:	NTUC		XE5375A		
2.	The finalized amount shall be:							
	(a)	Spare Parts af	ter List discount	٠				
	(b)	Labour Charge	.s					
	. ,	-	By-Part Repair Cost					
	(c.)		air (if applicable) sum repair cost after Less:					
		Final Lumpsu			-	\$2,950.00		
3.	Estim	nated normal peri	od for repairs:	<b>2</b> wo	orking days.			
						7		
4.		shall treat the ab ting days	ove amount as Correct and	d Confirmed if	there is no re	eply from you within 7		
5.	Thank you for your assistance.			We confirm the estimates and				
Thank you for your application.				fin				
	Signa	Signature :			Signature :			
Name : CHIANG				Name :		Theor		
	Tel	: 6214831	4	— Da	ate :	819/21		
	Fax	: 6546815		_ _				
For	Official	Use Only						
$\overline{}$				Document	Confirm By			
		Item	Amount	Attached Yes or No	(Signature)	Remarks		
1 0	lontal Dr	ate P/Day		YES				
Rental Rate P/Day     Loss of Income Paid			-	N				
	urvey Fe		-	-				
4. LTA Search Fee			\$7.49/\$2.00					
<ol><li>Medical Fees (on behalf of driver, if applicable)</li></ol>		ees (on behalf	-					
	verrun	п аррисавіе)						

Remarks:

REPAIR ESTIMATE\*

VEHICLE NO

SHC1248K

VEHICLE NO	SHC1248K	DATE	26/08/21	
MAKE	27.02.2019	57(1)	20,00,21	
MODEL	: HYUNDAI IONIQ G2		CHIANG /NTUC	
Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	FRONT BUMPER COVER			\$430.90
1	1 RADIATOR GRILLE			\$1,409.10
1	1 FRONT CENTRE MOULDING	1		\$368.50 /500
1	1 HEAD LAMP LH		(,(98.8	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
1	BUMPER CLIP		,	\$22.00 /nec
	1 FRONT NUMBER PLATE MOUNTING			\$188.00 \$500
		1		\$4,412.15
	20.00%	ı		\$882.43
	DISCOUNTED TOTAL	1		\$3,529.72
	1 NUMBER PLATE W/HOLDER			
	WATE WATE WATER			\$55.00
				\$55.00
	Labour Charge			1
	Panel Beating			4
	Spray Paint		£	\$550.00 350
	Check lighting			\$300.00 250
	TOTAL LABOUR			\$60.00 3 <i>o</i>
		1		\$510.00
	ESTIMATE TOTAL			\$4,494.72
				ψ1,134.7 <u>L</u>
	LKK Auto Consultants hence notify			
	the Repairer of the following:  To resurvey before/after spray painting			
	<ul> <li>To display damaged part(s) during resurvey</li> </ul>			
	<ul> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> </ul>			
	<ul> <li>No illegal modification(s) is allowed</li> </ul>			
	<ul> <li>Supplementary item(s) must be resurveyed <u>and</u></li> <li>is subject to final approval from Insurance Company</li> </ul>			
	Acknowledged by Repairer			
	Signature:			
	Date:			
		l.,,		
	This is an initial estimate based on a visual inspection of th			
	be prepared after the vehicle is surveyed by a motor Surv	eyon appoin	ited by the insurance c	ompany.
	Thuran LAY	the Hhod	Repailer of the following:	
	82235769 thevan@lhkayto.lom	• To:	display in hear ca yelledit	may .
			S smost when	
	26/8/21 1645	No - No.		
	•	SL. D.	ugjes 10/9% - Yosat	
	2 days wp			
	L/S after repair photos	Acknowlers  Signatsigns	owledgebby:Repairor	
	-/ 100 10011 10000	Date: Date:		
		THE PERSON NAMED IN		