



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8480J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	FRT BUMPER SIDE BRACKET LH /	SERVICEABLE	81.70	-
1	FRT BUMPER COVER	CUT	499.90	499.90
1	FRT BUMPER CENTRE GRILLE	SERVICEABLE	166.90	-
1	FRT BUMPER LOWER GRILLE	SERVICEABLE	301.90	-
1	FRT BUMPER TOW COVER	SERVICEABLE	28.38	-
1	FRT GRILLE EMBLEM	SERVICEABLE	88.00	-
1	FRT BUMPER LH GARNISH	SERVICEABLE	86.50	-
1	FRONT NUMBER PLATE MTG BRACKET	CUT	99.00	99.00
1	FRT BUMPER SIDE RETAINER /LH	SERVICEABLE	77.00	-
	LESS 25% DISCOUNT		-357.32	-149.73
			1,071.96	449.17
	<u>NETT ITEMS</u>			
1	FRONT NUMBER PLATE W/HOLDER (N)	CUT	55.00	55.00
	LESS 10% DISCOUNT		-	-5.50
			55.00	49.50
	<u>LABOUR</u>			
	PANEL BEATING.		750.00	350.00
	SPRAY PAINTING CHARGE.		600.00	250.00
	CHECK WIRING & LIGHTING.		60.00	30.00
	TUFF COAT.		60.00	30.00
			1,470.00	660.00
	GRAND TOTAL		2,596.96	1,158.67
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,158.67

Report Ref No. NS/INC21009155/Vvce2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.