

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III21009163/AGA3Q2**Date:** 19/01/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549\_01

**Claimant Vehicle No :** SJT2130X **Insured Vehicle No :** GBK3190H

Date of Loss: 30/08/2021 Nature of Claim: TP Claim No: MFL2021D0004098

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT2130X**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4927594

Reg. Date: 29/09/2009 (Man. Year: 2009) Chassis No: MR053ZEE106154069

Colour: Silver Odometer: 102901 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,108.47	1,338.75	1,769.72	56.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	530.00	1,550.00	74.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,188.47</b>	<b>1,868.75</b>	<b>3,319.72</b>	<b>63.98</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,188.47</b>	<b>1,400.00</b>	<b>3,788.47</b>	<b>73.02</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 30/08/2021

Date Inspected: 31/08/2021 Inspected At: SM Automotive (HQ)  
756 JURONG WEST STREET 74, #12-60  
Singapore 640756

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2022)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJT2130X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	689.60 FL	*- FL
2	1		*BONNET LOCK	Not Necessary	250.60 FL	*- FL
3	1		*BONNET RUBBER	Not Necessary	18.60 FL	*- FL
4	1		*FRONT BUMPER	Deformed	586.30 FL	*586.30 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	486.30 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	75.40 FL	*38.00 FL
7	1		*FRONT BUMPER FOG LAMP RH	Cracked	254.10 FL	*254.10 FL
8	1		*FRONT BUMPER FOG LAMP OUTER GARNISH RH	Cracked	85.40 FL	*85.40 FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	130.20 FL	*- FL
10	1		*RH FRONT HEADLAMP	Cracked	781.20 FL	*781.20 FL
11	1		*RH FRONT HEADLAMP LOWER BRACKET	Not Necessary	58.60 FL	*- FL
12	1		*FRONT GRILLE	Not Necessary	389.40 FL	*- FL
13	1		*FRONT GRILLE LOGO	Not Necessary	85.60 FL	*- FL
14	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
15	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
16	1		*FRONT NUMBER PLATE WITH CASING	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,081.30</b>	<b>1,775.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	972.83	436.25
<b>Total Parts (\$)</b>	<b>3,108.47</b>	<b>1,338.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING	New	1,000.00	300.00
2	LABOUR FOR SPRAY PAINTING	New	800.00	200.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS	New	200.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,080.00</b>	<b>530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >