

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009167/APA3Q2**Date:** 07/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700086556
Claimant Vehicle No :	SGG9555L	Insured Vehicle No :	SLU5728Z
Date of Loss:	21/08/2021	Nature of Claim:	TP
		Claim No:	8569996811SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG9555L	Engine No:	11628262N55B30A
Make & Model:	BMW 740LI, 3.0 SR LED (A)	Chassis No:	WBAYE42090DD87097
Reg. Date:	27/09/2012 (Man. Year: 2012)	Odometer:	121299 km
Colour:	Black		
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/30 R22	Rear Tyre Size:	265/30 R22
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,834.70	130.00	4,704.70	97.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,840.00	740.00	2,100.00	73.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,674.70	870.00	6,804.70	88.66
+ GST 7.00/7.00% (\$\$)	537.23	60.90	476.33	88.66
Nett Amount (\$\$)	8,211.93	930.90	7,281.03	88.66
+ Loss of Use (3.0 x S\$100.00/day) (\$\$)		300.00		
Nett Liability (\$\$)		1,230.90		
Global Sum Settlement (\$\$)		1,230.00		

INSPECTION

Date of Assignment:	30/08/2021		
Date Inspected:	30/08/2021	Inspected At:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,153.00 FL	*- FL
2	1		*RHS BUMPER CAMERA	Not Necessary	980.00 FL	*- FL
3	1		*RHF RIM (LOCAL REPAIR)	Cut	1,305.00 FS	*100.00 FS
4	1		*TIRE PRESSURE SENSOR	Not Necessary	700.00 FL	*- FL
5	1		*SET FRT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
					Sub Total (\$\$)	5,218.00 130.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	383.30 0.00
					Total Parts (\$\$)	4,834.70 130.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,400.00	250.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	800.00	250.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	80.00	30.00
4	REMOVE & REFIT TIRE	New	50.00	0.00
5	TO REMOVE AND REFIX FRT SENSOR AND CONDUCT TEST	New	180.00	60.00
6	TO REMOVE AND REFIX CAMERA AND CONDUCT TEST	New	180.00	60.00
7	TO CONDUCT 4 WHEEL ALIGNMENT	New	150.00	90.00
Gross Labour Cost (\$\$)			2,840.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >