

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21009170/KVCN2**Date:** 24/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00187292000

**Claimant Vehicle No :** SBN6888T **Insured Vehicle No :** SJL9146Y

Date of Loss: 27/08/2021 Nature of Claim: TP Claim No: SNM21D204853/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SBN6888T**

Make & Model: TOYOTA ESTIMA, 2.4 AERAS (A) Engine No: 2AZH971028

Reg. Date: 10/05/2013 (Man. Year: 2013) Chassis No: ACR507116529

Colour: Metallic Blue Odometer: 116689 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18

Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,407.50	934.00	473.50	33.64
Miscellaneous Items	320.00	320.00	0.00	0.00
Labour	1,830.00	1,360.00	470.00	25.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>3,557.50</b>	<b>2,614.00</b>	<b>943.50</b>	<b>26.52</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,600.00</b>		
<b>(\$\$)</b>	3,557.50	2,600.00	957.50	26.91
<b>+ GST 7.00/7.00% (\$\$)</b>	249.03	182.00	67.03	26.92
<b>Nett Amount (\$\$)</b>	<b>3,806.53</b>	<b>2,782.00</b>	<b>1,024.53</b>	<b>26.92</b>

**INSPECTION**

Date of Assignment: 31/08/2021 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)  
10 ANG MO KIO IND PARK 2A

Date Inspected: 11/10/2021 Inspected At: #01-04 ANG MO KIO AUTOPOINT  
SINGAPORE 568047

Estimated Period of Repair: 4.0 days REPAIRER:CHENG HOE MOTOR SERVICE

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2022)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBN6888T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc rear bumper	Buckled	280.00 F	*280.00 FL
2	1		*5 pcs rear bumper clips @ \$1.50/pc	Necessary	7.50 F	*7.50 FL
3	1		*1 pc tailgate	Bent	600.00 F	*600.00 FL
4	1		*1 pc tailgate inner rubber	Torn	125.00 F	*125.00 FL
5	1		*1 pc tailgate inner lock outer cover	Dented	24.00 F	*24.00 FL
6	1		*1 pc tailgate logo	Necessary	25.00 F	*25.00 FL
7	1		*1 pc tailgate emblem Estima	Necessary	28.00 F	*28.00 FL
8	1		*1 pc tailgate emblem Aeras	Necessary	28.00 F	*28.00 FL
9	1		*1 set tailgate windscreen glass moulding	Necessary	50.00 F	*50.00 FL
10	1		*1 pc rear end panel	Repair	240.00 F	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					1,407.50	1,167.50
- List Item Discount on L Items 0.00/20.00% (\$\$)					0.00	233.50
Total Parts (\$\$)					1,407.50	934.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	1 set reverse sensors (4pcs) Dented	280.00	280.00
2	1	1 unit rear windscreen glass sealant Necessary	40.00	40.00
<b>Sub Total (\$\$)</b>			<b>320.00</b>	<b>320.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	Remove & refix rear windscreen glass	New	120.00	120.00
2	Remove & refix rear bumper & parking sensors,tailgate & attachments;to cut,weld & renew rear end panel;knocking & repair rear luggage panel & realign the same	New	700.00	500.00
3	Putty & respray rear bumper & parking sensors,tailgate,rear end panel,rear luggage panel & all affected areas	New	800.00	600.00
4	Remove & refix reverse camera,reset & realign the same	New	50.00	50.00
5	Remove & refix rear seats,garnish to faciitate repair	New	100.00	60.00
6	Rustproofing	New	60.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,830.00</b>	<b>1,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >