

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE		Ref:	CS3/ASM21009173/Vtce2		
	8 SHENTON WAY SINGAPORE 0688		Date:	10/09/2021		
	ATTN: TEO KITTY			Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHB 2037B	Veh. Inspected	l	FBR 3214L	
	Policy No.	VFX/P2419140	Coverage (\$)		0.00	
	Claim No.	S1M03FSO	Excess (\$)		0.00	
	Assign From	TEO KITTY	Assign Date		01/09/2021	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA XMAX300	c.c		292	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	MH3SH0844KK008670	Colour		SILVER	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	130/70-15	BRIDGESTONE		7 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	130/70-15	BRIDGESTONE		7 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.			NT		
5.	5. General Information					
	Accident Date	14/08/2021	Inspect Date /	Time	02/09/2021 (11:16 AM)	
	Survey held at EQUATOR BROTHERHOOD					
	25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800					
5a.	ia. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500-\$5,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/ASM21009173/Vtce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser