

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21009174/Euce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 10/09/2021 SINGAPORE 068811 ATTN: CHAN KIAN CHUAN Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHA 9055H SJF 7001B Veh. Inspected Policy No. VFX/P2419140 Coverage (\$) 0.00 Claim No. S1M03GPM Excess (\$) 0.00 **CHAN KIAN CHUAN Assign Date** 01/09/2021 Assign From **Vehicle Particulars & Condition** 2. **TOYOTA CAMRY** c.c Make & Model 1998 2012 HIDDEN Engine No. Year of Reg. MR053BK5104000762 **GREY** Chassis No. Colour Odometer 123135 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 215/60 R16 MICHELIN 4 mm **MICHELIN** L/H Front Tyre 215/60 R16 4 mm 215/60 R16 **MICHELIN** R/H Rear Tyre 4 mm MICHELIN 4 mm L/H Rear Tyre 215/60 R16 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 26/08/2021 07/09/2021 ( 01:22 PM ) Inspect Date / Time Accident Date GRACE TEAM ENTERPRISE PTE LTD Survey held at 40 TOH GUAN ROAD EAST #01-61 SINGAPORE 608582 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 5b. **Estimate Days of Repair** 

Report Ref No. CS3/ASM21009174/Euce2

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

CHEN TSUE YEE

K.K.LAU CPT(RET)

**Automotive Assessor** 

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

5 Working Days