

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009175/KEA3Q2**Date:** 05/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900260945
Claimant Vehicle No :	SGC6543L	Insured Vehicle No :	SMR4332S
Date of Loss:	27/08/2021	Nature of Claim:	TP
		Claim No:	5186991393SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGC6543L	Engine No:	G4FGFH796890
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFX411MF5522351
Reg. Date:	17/12/2015 (Man. Year: 2015)	Odometer:	71233 km
Colour:	Metallic Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,156.40	5,031.88	3,124.52	38.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,580.00	910.00	36.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,646.40	6,611.88	4,034.52	37.90
Approved Total (Overridden) (S\$)		5,250.00		
(S\$)	10,646.40	5,250.00	5,396.40	50.69
+ GST 7.00/7.00% (S\$)	745.25	367.50	377.75	50.69
Nett Amount (S\$)	11,391.65	5,617.50	5,774.15	50.69
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,039.50		

INSPECTION

Date of Assignment:	01/09/2021	Chew Goon Motor (AMK)
Date Inspected:	01/09/2021 Inspected At:	Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Estimated Period of Repair:	5.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	856.00 FL	*688.00 FL
2	12		*REAR BUMPER CLIPS	Necessary	54.00 FL	*54.00 FL
3	1		*REAR BUMPER SPONGE	Serviceable	235.00 FL	*- FL
4	2		*REAR BUMPER BRACKETS	Cracked	78.00 FL	*78.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	434.00 FL	*350.00 FL
6	1		*REAR BUMPER LOWER LIP	Dented / Cut	245.00 FL	*245.00 FL
7	2		*REAR BUMPER REFLECTORS	Cut / Scratched	264.00 FL	*190.00 FL
8	3		*REAR BUMPER LOWER RETAINERS	Cracked	135.00 FL	*135.00 FL
9	1		*REAR BUMPER AUTO BOOT SENSOR	Serviceable	125.00 FL	*- FL
10	1		*BOOT EMBLEM	Necessary	43.00 FL	*43.00 FL
11	1		*BOOT BADGE FORTE	Necessary	42.00 FL	*42.00 FL
12	1		*BOOT BADGE K3	Necessary	39.00 FL	*39.00 FL
13	1		*END PANEL	Repair	335.00 FL	*- FL
14	1		*END PANEL GARNISH	Mtg Distorted	165.00 FL	*165.00 FL
15	1		*FRONT BUMPER	Mtg Cracked	820.00 FL	*745.20 FL
16	10		*FRONT BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
17	1		*FRONT BUMPER SPONGE	Cracked	116.00 FL	*116.00 FL
18	1		*FRONT BUMPER REINFORCEMENT	Bent	423.00 FL	*313.00 FL
19	1		*FRONT BUMPER NUMBER PLATE HOLDER	Cracked	47.00 FL	*47.00 FL
20	1		*FRONT BUMPER CENTER AIR GRILLE	Dented	79.00 FL	*79.00 FL
21	1		*FRONT BUMPER EMBLEM	Necessary	42.00 FL	*42.00 FL
22	1		*GRILLE	Dented	324.00 FL	*324.00 FL
23	1		*HEADLAMP ASSY (HID)	N/S Mtg Cracked	3,700.00 FL	*1,523.00 FL
24	1		*REAR BUMPER REVERSE SENSOR	Cut	280.00 FS	*200.00 FS
25	1		*BOOT BADGE C&C	Necessary	50.00 FS	*50.00 FS
26	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,021.00	5,558.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	864.60	526.32
Total Parts (\$\$)	8,156.40	5,031.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT REAR ELECTRICAL CHECK ,REPLACE REVERSE SENSORS ,MODULE REWIRING ETC	New	120.00	50.00
2	TO DISMANTLE /REFIT TRUNK COMPARTMENT BOARDS & TRIMS	New	80.00	0.00
3	TO SUPPLY END PANEL BODY SEALANT	New	60.00	0.00
4	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	100.00	0.00
5	TO CONDUCT FRONT ELECTRICAL CHECK ,FOCUS HEADLAMP	New	30.00	30.00
6	LABOUR CHARGE -PANEL BEATING ,REPAIRING REAR CHASSIS MEMBER ,BOOT LID ,FLOOR PANEL,SPARE TYRE PANEL ,FRONT SUPPORT ETC .CNT ,WELD END PANEL AND PARTS REPLACEMENT	New	1,100.00	700.00
7	TO RESPRAY AFFECTED AREAS (BIG VEH)	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,490.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >