

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21009180/AUCN2**Date:** 05/11/2021**REFERENCE****Insured/Claimant:** HENG CHIANG YONG(WANG CHANGRONG)**Policy No:** 1700037768**Date of Loss:** 06/07/2021**Nature of Claim:** OD**Claim No:** 1619428793SG**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SJE8785X**Make & Model:** AUDI A3, 999cc TFSI S TRONIC (LED) (A)**Engine No:** CHZ508444**Reg. Date:** 10/08/2017 (Man. Year: 2017)**Chassis No:** WAUZZZ8VXJ1004664**Colour:** Black**Odometer:** 76221 km**Engine Capacity:** 999 cc**Market Value/New Car Price:** S\$75,000.00**Sum Insured (S\$):** **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Steering (Serviceable):

Yes

**Footbrake (Serviceable):**

Yes

**Handbrake (Serviceable):** Yes **Engine Modification:**

No

**Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 205/55R16**Rear Tyre Size:** 205/55R16**Front Left Side:** Yokohama 6 mm**Rear Left Side:** Yokohama 6 mm**Front Right Side:** Yokohama 6 mm**Rear Right Side:** Yokohama 6 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,370.00	189.60	3,180.40	94.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,422.00	1,522.00	900.00	37.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,792.00</b>	<b>1,711.60</b>	<b>4,080.40</b>	<b>70.45</b>
<b>+ GST 7.00/7.00% (S\$)</b>	405.44	119.81	285.63	70.45
<b>Nett Amount (S\$)</b>	<b>6,197.44</b>	<b>1,831.41</b>	<b>4,366.03</b>	<b>70.45</b>

**INSPECTION****Date of Assignment:** 01/09/2021**Date Inspected:** 31/08/2021**Inspected At:**

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

**Estimated Period of Repair:** 3.0 days**Adjuster:** ADRIAN LING**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,944.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS
3	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	32.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Deformed	237.00 FS	*189.60 FS
5	1		*REAR BUMPER REFLECTOR-LH	Not Necessary	41.00 FS	*- FS
6	2		*REAR BUMPER PARKING AID SENSOR (Npa)	Not Necessary	0.00 FS	*- FS
7	4		*REAR BUMPER PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
8	1		*REAR BUMPER REINFORCEMENT	Not Necessary	603.00 FS	*- FS
9	2		*REAR BUMPER BRACKET-LH/RH	Not Necessary	56.00 FS	*- FS
10	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (S\$)</b>	<b>3,370.00      189.60</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>2,422.00</b>	<b>1,522.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >