

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	L INSURANCE (S) PL	R	ef:	CS/AGI21009181/Uuf3n2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	28/09/2021	
			С	ode:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SCM 9868A	Veh. Inspected		SJX 7665R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	10011482/JM	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		01/09/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI AVANTE (A)	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	KMHDU41BMAU986623	Colour		BLACK	
	Odometer	187721 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/60 R15	FIRENZA		6 mm	
	L/H Front Tyre	195/60 R15	FIRENZA		6 mm	
	R/H Rear Tyre	195/60 R15	HABILEAD		6 mm	
	L/H Rear Tyre	195/60 R15	HABILEAD		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	29/08/2021	Inspection Date		01/09/2021	
	Survey held at Blk 15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE					
	Repairer	epairer ZOOM AUTOWERKS PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: