

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21009182/R1VF3E2

**Date:** 08/09/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900077584		
<b>Claimant Vehicle No :</b>	FBA8159U	<b>Insured Vehicle No :</b>	SMH9021J		
Date of Loss:	31/05/2021	Nature of Claim:	TP	Claim No:	8255139200SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBA8159U</b>	Engine No:	NC23E3100272
Make & Model:	HONDA CB400, 399cc	Chassis No:	JH2NC39966M200261
Reg. Date:	25/08/2006 (Man. Year: 2006)	Odometer:	362870 km
Colour:	Black		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	150/60 R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	01/09/2021		
Date Inspected:	02/09/2021	Inspected At:	EQUIPMENT EXTREME (HQ) 4001, DEPOT LANE, #01-10 Singapore 109755
Estimated Period of Repair:	4.0 days		

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$11,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Scratched	0.00 F	*- F
2	1		*FRONT HEADLAMP FAIRING	Scratched	0.00 F	*- F
3	1		*FRONT WING MIRROR LH	Scratched	0.00 F	*- F
4	1		*HANDLE BAR BALANCER LH	Scratched	0.00 F	*- F
5	1		*FUEL TANK	Repair	0.00 F	*- F
6	1		*CLUTCH LEVER	Scratched	0.00 F	*- F
7	1		*SIDE FAIRING LH	Cracked	0.00 F	*- F
8	1		*ENGINE CRASH BAR	Scratched	0.00 F	*- F
9	1		*FRONT FOOT REST LH	Cracked	0.00 F	*- F
					<b>Total Parts (S\$)</b>	<b>0.00 0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >