

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG21009184/UQF3E2

Date: 01/10/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29146062

Claimant Vehicle No : EH3737L

Insured Vehicle No : YN921Y

Date of Loss: 31/08/2021

Nature of Claim: TP

Claim No: 637808

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EH3737L**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A)

Engine No: 1ZRX499381

Reg. Date: 06/04/2015 (Man. Year: 2015)

Chassis No: MR053REH104529810

Colour: Silver

Odometer: 159240 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Firenza 6 mm

Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,969.40	2,401.79	7,567.61	75.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	2,100.00	1,750.00	45.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,819.40	4,501.79	9,317.61	67.42
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	13,819.40	3,500.00	10,319.40	74.67
+ GST 7.00/7.00% (S\$)	967.36	245.00	722.36	74.67
Nett Amount (S\$)	14,786.76	3,745.00	11,041.76	74.67

INSPECTION

Date of Assignment: 03/09/2021

Date Inspected: 01/09/2021 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EH3737L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,266.10 F	*- FL
2	1		*BOOTLID REAR LOGO	Not Necessary	68.50 F	*- FL
3	1		*BOOTLID COROLLA EMBLEM	Not Necessary	62.80 F	*- FL
4	1		*BOOTLID ALTIS EMBLEM	Not Necessary	58.00 F	*- FL
5	1		*BOOTLID INNER LOCK	Serviceable	409.10 F	*- FL
6	1		*BOOTLID LOCK STRICKER	Not Necessary	66.80 F	*- FL
7	1		*BOOTLID WEATHERSTRIP	Twisted	282.30 F	*169.39 FL
8	2		*BOOTLID REFLECTORS	Not Necessary	901.80 F	*- FL
9	1		*BOOTLID INNER TRIM	Not Necessary	366.10 F	*- FL
10	1		*REAR BUMPER	Dented / Deformed	655.10 F	*492.20 FL
11	1		*REAR BUMPER BEAM	Dented	505.40 F	*361.60 FL
12	2		*REAR BUMPER REFLECTORS	Not Necessary	120.00 F	*- FL
13	2		*REAR BUMPER SIDE RETAINERS	Necessary	130.00 F	*130.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
15	1		*REAR END PANEL	Dented	788.20 F	*581.20 FL
16	1		*REAR END PANEL TOP GARNISH	Twisted	362.30 F	*184.20 FL
17	2		*TAILLAMPS	Holder Cracked	1,160.00 F	*823.46 FL
18	2		*TAILLAMP LOWER BRACKETS	Cracked	130.00 F	*77.00 FL
19	1		*REAR ANTENNA SENSOR	Not Necessary	241.20 F	*- FL
20	1		*REAR FLOOR PANEL	Repair	1,145.20 F	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	620.50 F	*- FL
22	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
23	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
24	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,969.40	3,119.05
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	717.26

Total Parts (\$\$)	9,969.40	2,401.79
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	100.00	0.00
4	TO DISMANTLE & REFIX CUSION UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	100.00	40.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,600.00	800.00
7	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,100.00
Gross Labour Cost (\$\$)			3,850.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >