

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009186/VEA3Q2
Date: 10/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210034751
Claimant Vehicle No :	SH7961M	Insured Vehicle No :	SMZ3268J
Date of Loss:	31/08/2021	Nature of Claim:	TP
		Claim No:	6560457388SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7961M		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU404268
Reg. Date:	30/10/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU188677
Colour:	Blue	Odometer:	186159 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,325.16	2,093.16	232.00	9.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	2,050.00	220.00	9.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,595.16	4,143.16	452.00	9.84
+ GST 7.00/7.00% (S\$)	321.66	290.02	31.64	9.84

Nett Amount (S\$)	4,916.82	4,433.18	483.64	9.84
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$125.19/day) (S\$)		500.76		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,135.94		
Global Sum Settlement (S\$)		5,130.00		

INSPECTION

Date of Assignment: 01/09/2021

Date Inspected: 01/09/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: Thevan Thomas Karthikesavan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH FENDER	Deformed	588.80 FL	*588.80 FL
2	10		*FRT RH FENDER EMBLEM	Necessary	26.60 FL	*26.60 FL
3	1		*FRT RH DOOR ASSY	Deformed	1,797.20 FL	*1,797.20 FL
4	1		*ROCKER PANEL GARNIS RH	Repair	290.00 FL	*- FL
5	1		*FRT RH DOOR PROTECTOR RH	Scratched	110.10 FL	*110.10 FL
6	1		*FRT DOOR COMFORTDELGRO LOGO	Necessary	75.00 FS	*75.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,887.70	2,597.70
- List Item Discount on L Items 20.00/20.00% (\$)	562.54	504.54
Total Parts (\$)	2,325.16	2,093.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	700.00
2	SPRAY PAINT	New	1,250.00	1,250.00
3	CHECK WIRING	New	50.00	20.00
4	TUFF KOTE	New	50.00	20.00
5	TRANSFER DOOR PART	New	120.00	60.00
Gross Labour Cost (S\$)			2,270.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >