



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. SKG 6846U

Qty	Description of Parts	Condition	Recommended (\$)
<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT WINDSCREEN GLASS WITH MOULDING	CRACKED	1,350.40
	LESS 10% DISCOUNT		-135.04
			1,215.36
<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT WINDSCREEN GLASS SEALANT (SN)	NECESSARY	50.00
1	ERP BRACKET (SN)	NECESSARY	26.00
1	SET WIPER BLADE (SN)	CUT	60.00
			136.00
<b><u>LABOUR</u></b>			
	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS.		120.00
			120.00
<b>GRAND TOTAL</b>			<b>1,471.36</b>

<b>RECOMMENDED COST OF REPAIRS</b>	<b>1,471.36</b>
------------------------------------	-----------------

Report Ref No. CS/MSG21009193/Gqf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.