

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	MSIG INSURANCE	(SINGAPORE) PTE LTD	Ref:	CS/MSG21009194/Kvf3e2	
	4 SHENTON WAY #21-01,SGX CENTRE 2 SINGAPORE 068807		Date:	23/09/2021	
			Code:	MSG	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SJL 8198D	
	Policy No.	B 300445396 CAR	Coverage (\$)	0.00	
	Claim No.	261912 CAR	Excess (\$)	0.00	
	Assign From	ZI LIANG	Assign Date	01/09/2021	
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN TEANA (A)	c.c	1997	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	JN1BDUJ32Z0000482	Colour	METALLIC DARK BLUE	
	Odometer	132583 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/65 R16	YOKOHAMA	7 mm	
	L/H Front Tyre	205/65 R16	YOKOHAMA	7 mm	
	R/H Rear Tyre	205/65 R16	YOKOHAMA	7 mm	
	L/H Rear Tyre	205/65 R16	YOKOHAMA	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE BONNET, FRONT WINDSCREEN AND ROOF TOP FOUND DAMAGED AT THE TIME OF INSPECTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	27/08/2021	Inspection Date	02/09/2021	
	Survey held at	blk 5033 #01-251			
	Repairer GOLD PERFORMANCE PTE LTD				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	-		"		