

ASS. REG. BY:

REF:

MSG / 210091941KV

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of Amk 5033 01-251

Insured: Public Liability

Policy No. B300445396 CAR

Claims No. 261912 CAR

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

1-21 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Steven Ko

Vehicle: IN / OUT

97289234

Veh No:

STG 8198 D

Yr Regn:

2008

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS Tean

c.c 1997

Colour

M.D. Blue

AC:

Insured / Std / NI / NA

Sp. Reading

132 583

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1304J3280000482

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

205/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

27/8/21

D.O.I.

2/9/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Bonnet, Frt wheel &amp; roof by frontal impact

The U/C / Chassis frame / Body Structure affected due to collision.

at the time of inspection.

Date / Time

Action / Instruction

No GIA report

21/9/21

@4.47pm Final fig \$2145.95 confirmed with Gold (Red 859.11, 28%)

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2) 21/9/21-typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format : TP

Lump Sum / I.B.I: (\$ 2145.95



**GOLD PERFORMANCE PTE LTD**

Block 5033 Ang Mo Kio Industrial Park 2 #01-251/259

Singapore 569536

Mobile : 97289234

Email : goldperformancepl@gmail.com

UEN &amp; GST Registration no:202039762K

*Kenneth  
96910663**Not Authorized  
Painting After Rain  
Today***31.08.2021****QUOTATION****Q:20210801**Attention: Mr Marvin Chia  
cc: Vehicle Owner - Mr Tan Beng Yong

Email:marvin.chia@mclarens.com

Dear Sirs

**ESTIMATE REPAIR COST OF SJL8198D (NISSAN TEANA 200XL) MODEL WJ32 on an accident on 27.08.2021 at about 6pm on the premise of Takeda Manufacturing Singapore Pte Ltd. located at 2A Woodlands Industrial Park D, Street 2 Singapore 737779 (during excavation work by Boustead Sub-Contractors)**

Item	Description	Qty	Unit Price:S\$	Total:S\$
	To supply labour:-			
01	To knock/repair front bonnet and rooftop			180.00
02	To spray paint front bonnet, rooftop and all affected areas			<i>500</i> 650.00
03	Front WindScreen <i>10% CM</i>	1 pc	1,452.00	1,452.00
03 (a)	Front WindScreen Top Moulding <i>m</i>	1 pc	49.06	49.06
03 (b)	WindScreen Gum / Sealant <i>m</i>	1 set	44.00	44.00
03 (c)	Labour charges to remove and install WindScreen			150.00
04	Loss of Use, Car Rental - 4 days	4 days	120.00	480.00
				<b>\$ 3,005.06</b>

We hope that our quotation will meet with your kind approval.

Thank you.

Steven Ko  
97289234

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: