

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009196/UQC�2**Date:** 29/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMTPSNA00000362100

Claimant Vehicle No : SDD2277L **Insured Vehicle No :** SLN94M

Date of Loss: 20/08/2021 Nature of Claim: TP Claim No: SNM21D204791/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDD2277L**

Make & Model: LEXUS ES250, 2.5 (A) Engine No: 2ARE739339

Reg. Date: 09/12/2013 (Man. Year: 2013) Chassis No: JTHBJ1GG902033502

Colour: Black Odometer: 108091 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 ZR17 Rear Tyre Size: 215/55 ZR17

Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm

Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,165.93	2,400.61	4,765.32	66.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,130.00	1,220.00	51.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,515.93	3,530.61	5,985.32	62.90
Approved Total (Overridden) (\$\$)		2,800.00		
Nett Amount (\$\$)	9,515.93	2,800.00	6,715.93	70.58

INSPECTION

Date of Assignment: 01/09/2021

Date Inspected: 01/09/2021 Inspected At: Imperium Automotive - Kaki Bukit (HQ)
25 Kaki Bukit Road 4, #01-49 Synergy@KB
Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Sep 2021)
Parts:	143	LEXUS ES250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDD2277L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	954.10 FL	*- FL
2	1		*REAR BOOT LOGO	Necessary	81.70 FL	*81.70 FL
3	1		*REAR BOOT LEXUS EMBLEM	Necessary	68.20 FL	*68.20 FL
4	1		*REAR BOOT ES250 EMBLEM	Necessary	68.20 FL	*68.20 FL
5	1		*REAR BOOT LID REFLECTOR RH	Scratched	739.00 FL	*420.20 FL
6	1		*REAR BUMPER	Dented/Deformed	1,273.40 FL	*1,015.90 FL
7	1		*REAR BUMPER LOWER DIFFUSER	Not fitted	781.10 FL	*- FL
8	2		*REAR BUMPER PDC SENSORS	Not Necessary	760.00 FL	*- FL
9	1		*REAR BUMPER REFLRCTORS	Not Necessary	221.25 FL	*- FL
10	1		*SET REAR BUMPER CLIP	Necessary	65.00 FL	*60.00 FL
11	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	182.10 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Dented	771.25 FL	*771.25 FL
13	1		*REAR BUMPER SPONGE	Cracked	181.90 FL	*181.90 FL
14	1		*REAR EXHAUST SILENCER	Not Necessary	1,193.25 FL	*- FL
15	1		*REAR EXHAUST SILENCER END CAP	Not Necessary	430.00 FL	*- FL
16	3		*REAR EXHAUST MOUNTINGS	Not Necessary	191.70 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,962.15	2,667.35
- List Item Discount on L Items 10.00/10.00% (\$\$)	796.22	266.74
Total Parts (\$\$)	7,165.93	2,400.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	450.00
2	TO RESPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
3	TO APPLY UNDERCOATING	New	150.00	0.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE,REPLACE DAMAGED LAMP AND CHECK FRONT WIRING	New	100.00	30.00
Gross Labour Cost (\$\$)			2,350.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >