

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21009198/KQCE2**Date:** 26/10/2021**REFERENCE**

Insured/Claimant: Tsai Chen Cheng Policy No: DMPCSNW00025722100

Date of Loss: 28/08/2021 Nature of Claim: OD Claim No: SNM21D204842/C01/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SGN9117G**

Make &amp; Model: PEUGEOT 308, 1.6 GTI TURBO (M)

Engine No: VEDA01815

Reg. Date: 24/10/2012 (Man. Year: 2011)

Chassis No: VF34C5FU8BS322870

Colour: Metallic Red

Odometer: 176585 km

Engine Capacity: 1598 cc

Market Value/New Car Price: S\$22,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/40 R18

Rear Tyre Size: 225/40 R18

Front Left Side: Goodyear 9 mm

Rear Left Side: Goodyear 9 mm

Front Right Side: Goodyear 9 mm

Rear Right Side: Goodyear 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,672.00	4,472.00	200.00	4.28
Miscellaneous Items	265.00	265.00	0.00	0.00
Labour	306.60	273.00	33.60	10.96
Paintwork Labour	894.42	894.42	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,138.02</b>	<b>5,904.42</b>	<b>233.60</b>	<b>3.81</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
<b>- Excess (S\$)</b>	500.00	0.00	500.00	100.00
<b>(S\$)</b>	5,638.02	3,000.00	2,638.02	46.79
<b>+ GST 7.00/7.00% (S\$)</b>	394.66	210.00	184.66	46.79
<b>Nett Amount (S\$)</b>	<b>6,032.68</b>	<b>3,210.00</b>	<b>2,822.68</b>	<b>46.79</b>

**INSPECTION**

Date of Assignment: 01/09/2021 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Date Inspected: 02/09/2021 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #04-01, Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2021)
Parts:	144	PEUGEOT 308 1.6 GTI TURBO (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGN9117G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		4,672.00 F	*4,472.00 F
F=Franchise part.						
				Total Parts (S\$)	4,672.00	4,472.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Extra	265.00	265.00
Sub Total (\$\$)			265.00	265.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Including Material	New	894.42	894.42
<u>Labour Items</u>				
2	Total of Labour	New	306.60	273.00
Gross Labour Cost (\$\$)			1,201.02	1,167.42

Report was unsubmitted during this print-out.

< END OF ESTIMATES >