

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jacqueline Tan

Date: 02 Sep 2021

**Preliminary Advice**

Vehicle No	: SGN9117G	Accident Date	: 28/08/2021
Make	: PEUGEOT 308	Policy No.	: DMPCSNW00025722100
Assignment Date	: 01/09/2021	Excess	: S\$0.00
Date of Inspection	: 02/09/2021	Est. Duration of Repair	: 5
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,138.02
Revised Amount	:S\$	5,946.42
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,946.42
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	22,000.00
COE / PARF Rebate	:S\$	20,909.00
Salvage Value	:S\$	
Margin for Repair	:S\$	1,091.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : REPAIRER ABLE TO UNDERTAKE THE REPAIR COST AT \$3,000.00 ON LUMP SUM BASIS.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.