

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21009202/GQF3E2

Date: 23/03/2022

REFERENCE

Insured/Claimant:	KST AUTO RENTAL PTE LTD	Policy No:	0999993603	
Date of Loss:	26/08/2021	Nature of Claim:	OD	Claim No: 5567088246SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF635M		
Make & Model:	TOYOTA HIACE, 1.8 D SUPER GL DARK PRIME (A)	Engine No:	1KD2619760
Reg. Date:	10/06/2016 (Man. Year: 2016)	Chassis No:	JTFHT02P000197960
Colour:	Blue	Odometer:	0 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$45,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	DURATURN 6 mm	Rear Left Side:	DURATURN 6 mm
Front Right Side:	DURATURN 6 mm	Rear Right Side:	DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,527.61	10,953.80	2,573.81	19.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,005.00	3,790.00	1,215.00	24.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,532.61	14,743.80	3,788.81	20.44
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	17,532.61	13,743.80	3,788.81	21.61
+ GST 7.00/7.00% (S\$)	1,227.28	962.07	265.21	21.61
Nett Amount (S\$)	18,759.89	14,705.87	4,054.02	21.61

INSPECTION

Date of Assignment:	01/09/2021		
Date Inspected:	02/09/2021	Inspected At:	Kim Seng Teck Motor Works (HQ) 3021A Ubi Rd 1 #01-42 Singapore 408715
Estimated Period of Repair:	12.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Buckled	270.00 F	*270.00 F
2	1		*FRONT HEADLAMP (WCP)	Smashed	310.00 F	*310.00 F
3	1		*FRONT BUMPER (WCP)	Cracked	220.00 F	*220.00 F
4	1		*FRONT GRILLE (WCP)	Missing	318.18 F	*250.00 F
5	1		*FRONT BASE PANEL (WCP)	Not Necessary	254.55 F	*- F
6	2		*FRONT BUMPER BRACKET (WCP)	Not Necessary	100.00 F	*- F
7	1		*FRONT DOOR (WCP)	Bent	681.82 F	*680.00 F
8	2		*BUMPER RETAINERS (WCP)	Cut	140.00 F	*140.00 F
9	1		*FRONT WINDSCREEN GLASS (WCP)	Cracked	1,449.55 F	*180.00 F
10	1		*FRONT WINDSCREEN MOULDING (WCP)	Not Necessary	70.82 F	*- F
11	1		*SILICONE SEAL (WCP)	Necessary	44.00 F	*44.00 F
12	1		*ERP STICKER (WCP)	Not Necessary	7.73 F	*- F
13	1		*RADIATOR (WCP)	Bent	700.00 F	*700.00 F
14	4		*COOLANT (WCP)	Not Necessary	72.73 F	*- F
15	1		*FRONT NUMBER PLATE (WCP)	Bent	27.27 F	*11.00 F
16	1		*FRONT DOOR PILLAR (WCP)	Bent	227.27 F	*150.00 F
17	1		*SIDE MIRROR (WCP)	Distorted	200.00 F	*200.00 F
18	1		*FRONT DOOR GLASS (WCP)	Smashed	222.73 F	*230.00 F
19	1		*FRONT DOOR INNER LOCK (WCP)	Jammed	222.73 F	*220.00 F
20	1		*REAR LAMP (LH) (WCP)	Cracked	86.36 F	*50.00 F
21	1		*AIR CON COIL (WCP)	Distorted	1,250.00 F	*1,250.00 F
22	1		*AIR CON CONDENSER (WCP)	Bent	500.00 F	*500.00 F
23	1		*AIR CON BLK VALVE (WCP)	Not Necessary	59.09 F	*- F
24	1		*FRONT HEADLAMP (WCP) (SUPPLEMENTARY)	O/S Broken	620.00 F	*310.00 F
25	1		*FRONT FENDER (WCP) (SUPPLEMENTARY)	Buckled	80.00 F	*80.00 F
26	1		*FRONT GRILLE (TOP) (WCP) (SUPPLEMENTARY)	Distorted	120.00 F	*120.00 F
27	1		*FRONT GRILLE LOWER PANEL (WCP) (SUPPLEMENTARY)	Distorted	150.00 F	*150.00 F
28	1		*FRONT PANEL (WCP) (SUPPLEMENTARY)	Bent	40.00 F	*40.00 F
29	1		*FRONT DOOR WEATHERSTRIP (INNER) (WCP) (SUPPLEMENTARY)	Twisted	120.00 F	*120.00 F
30	1		*FRONT DOOR GLASS RUBBER (WCP) (SUPPLEMENTARY)	Deformed	60.00 F	*60.00 F
31	1		*INTER COOLAR (WCP) (SUPPLEMENTARY)	Bent	600.00 F	*600.00 F
32	1		*DOOR CHECK (WCP) (SUPPLEMENTARY)	Bent	80.00 F	*80.00 F
33	1		*FRONT BONNET CABLE (WCP) (SUPPLEMENTARY)	Broken	55.00 F	*55.00 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*FRONT BONNET LOCK (WCP) (SUPPLEMENTARY)	Bent	70.00 F	*70.00 F
35	1		*FRONT DOOR RUBBER (WCP) (SUPPLEMENTARY)	Twisted	170.00 F	*170.00 F
36	1		*WIPER LINK (WCP) (SUPPLEMENTARY)	Bent	250.00 F	*250.00 F
37	2		*DOOR HINGE (WCP) (SUPPLEMENTARY)	Bent	110.00 F	*110.00 F
38	1		*FRONT LH PILLAR OUT (WCP) (SUPPLEMENTARY)	Bent	240.00 F	*240.00 F
39	1		*PANEL LH COWL TOP (WCP) (SUPPLEMENTARY)	Deformed	60.00 F	*60.00 F
40	1		*HEADLAMP MTG BRACKET (WCP) (SUPPLEMENTARY)	Broken	50.00 F	*50.00 F
41	1		*DOOR STRIKER (WCP) (SUPPLEMENTARY)	Bent	35.00 F	*35.00 F
42	1		*FRONT BUMPER GRILLE LH (WCP) (SUPPLEMENTARY)	Missing	40.00 F	*40.00 F
43	1		*FRONT DOOR SUDUFF PLATE LH (WCP) (SUPPLEMENTARY)	Bent	130.00 F	*130.00 F
44	1		*HEADLAMP BRACKET (WCP) (SUPPLEMENTARY)	Broken	15.00 F	*15.00 F
45	2		*FRONT BONNET HINGES (WCP) (SUPPLEMENTARY)	Bent	80.00 F	*80.00 F
46	1		*FRONT DOOR REGULATOR (WCP) (SUPPLEMENTARY)	Bent	120.00 F	*120.00 F
47	1		*RADIATOR SPARE TANK (WCP) (SUPPLEMENTARY)	Deformed	180.00 F	*180.00 F
48	1		*WIPER TANK (WCP) (SUPPLEMENTARY)	Deformed	60.00 F	*60.00 F
49	1		*SUPPORT PANEL (WCP) (SUPPLEMENTARY)	Buckled	180.00 F	*180.00 F
50	1		*RADIATOR FAN COWLING (WCP) (SUPPLEMENTARY)	Deformed	140.00 F	*140.00 F
51	1		*EMBLEM (WCP) (SUPPLEMENTARY)	Necessary	40.00 F	*40.00 F
52	1		*FRONT DOOR CARDBOARD (WCP) (SUPPLEMENTARY)	Deformed	400.00 F	*400.00 F
53	6		*CLIP (WCP) (SUPPLEMENTARY)	Necessary	18.00 F	*18.00 F
54	1		*AIR CON BLOW SYSTEM (WCP) (SUPPLEMENTARY)	Distorted	550.00 F	*550.00 F

F=Franchise part.

Sub Total (\$\$)	12,297.83	9,958.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,229.78	995.80
Total Parts (\$\$)	13,527.61	10,953.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR REMOVE & REFIX AIR CON SYSTEM AND REFILL GAS	New	180.00	120.00
2	LABOUR FOR REMOVE & REFIX WINDSCREEN	New	120.00	120.00
3	LABOUR FOR REPAIR LIGHT WIRING	New	60.00	40.00
4	TO CHECK FROM WIRING & FRONT HEADLAMP	New	40.00	20.00
5	TO DISMANTLE & REFIX CABIN LH HANDSIDE CARPET & TRIMING	New	160.00	120.00
6	TO RESPRAY PAINT FROM AFFECTED PORTION	New	1,500.00	1,400.00
7	TO STRAIGHTEN & KNOCK & CUT AFFECTED PANEL & RENEW RECOMMENED PARTS	New	1,800.00	1,700.00
8	TO DISMANTLE & REFIX REAR CABIN TRIMING & GARNISH TO ENABLE REPAIR	New	45.00	20.00
9	TO SPRAY PAINT LH REAR PORTION	New	800.00	0.00
10	LABOUR FOR REMOVE & REFIX DASHBOARD	New	300.00	250.00
Gross Labour Cost (S\$)			5,005.00	3,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >