

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21009203/TPA3Q2**Date:** 28/09/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800096280
<b>Claimant Vehicle No :</b>	JPK3064	<b>Insured Vehicle No :</b>	SMD3605K
Date of Loss:	24/02/2021	Nature of Claim:	TP
		Claim No:	1195054949SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>JPK3064</b>	Engine No:	G399EE116260
Make & Model:	YAMAHA 135LC, 135cc ES	Chassis No:	PMYKG0540D0116260
Reg. Date:	05/06/2013 (Man. Year: 2013)	Odometer:	0 km
Colour:	Red/Black		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	70/90 R17	Rear Tyre Size:	80/90 R17
Front Left Side:	DIAMOND 5 mm	Rear Left Side:	DIAMOND 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,369.00	4,832.10	536.90	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	780.00	250.00	24.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>6,399.00</b>	<b>5,612.10</b>	<b>786.90</b>	<b>12.30</b>
<b>+ Loss of Use (7.0 x S\$30.00/day) (S\$)</b>		210.00		
	<b>Nett Liability (S\$)</b>	<b>5,822.10</b>		

**INSPECTION**

Date of Assignment:	01/09/2021		
Date Inspected:	06/09/2021	Inspected At:	Pang Scooter Service (HQ) BLK 1006 BUKIT MERAH LANE 2 #01-06 Singapore 159762
Estimated Period of Repair:	7.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLIGHT ASSY	Missing	185.00 F	*185.00 FL
2	1		*METER ASSY	Cracked	320.00 F	*320.00 FL
3	1		*SIGNAL LIGHT ASSY	Cracked	165.00 F	*165.00 FL
4	1		*HANDLE BAR	Bent	98.00 F	*98.00 FL
5	1		*HANDLE BRACKET	Bent	85.00 F	*85.00 FL
6	1		*COWLING STAY	Bent	65.00 F	*65.00 FL
7	1		*STEERING CON	Necessary	110.00 F	*110.00 FL
8	1		*UNDLER BRACKET	Bent	195.00 F	*195.00 FL
9	2		*FORK ASSY X2	Bent	380.00 F	*380.00 FL
10	1		*FRONT FENDER	Cracked	85.00 F	*85.00 FL
11	1		*FRONT WHEEL SHAFT	Bent	45.00 F	*45.00 FL
12	1		*FRONT WHEEL RIM	Bent	398.00 F	*398.00 FL
13	1		*FRONT BRAKE DISC	Bent	185.00 F	*185.00 FL
14	1		*FRONT HANDLE COVER UPPER	Distorted	95.00 F	*95.00 FL
15	1		*REAR HANDLER COVER UPPER	Deformed	85.00 F	*85.00 FL
16	1		*TOP FRONT PANEL	Cut	195.00 F	*195.00 FL
17	1		*PANEL COVER	Deformed	110.00 F	*110.00 FL
18	1		*PANEL INNER (I)	Deformed	80.00 F	*80.00 FL
19	1		*MIRROR	Missing	45.00 F	*45.00 FL
20	1		*BRAKE LEVER	Bent	110.00 F	*110.00 FL
21	1		*METER GEAR	Distorted	85.00 F	*85.00 FL
22	1		*L/H LEG SHIELD	Distorted	185.00 F	*185.00 FL
23	1		*R/H LEG SHIELD	Distorted	185.00 F	*185.00 FL
24	1		*L/H FRONT BODY LOWER	Deformed	45.00 F	*45.00 FL
25	1		*R/H FRONT BODY LOWER	Deformed	45.00 F	*45.00 FL
26	1		*L/H AIR GUIDE	Deformed	25.00 F	*25.00 FL
27	1		*R/H AIR GUIDE	Deformed	25.00 F	*25.00 FL
28	1		*RADIATOR	Bent	380.00 F	*380.00 FL
29	1		*COOLANT	Necessary	35.00 F	*35.00 FL
30	1		*WINDSHIELD	Missing	68.00 F	*68.00 FL
31	1		*REAR BOX	Distorted	580.00 F	*580.00 FL
32	1		*BOX REAR	Bent	180.00 F	*180.00 FL
33	1		*EXHAUST ASSY	Bent	495.00 F	*495.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,369.00</b>	<b>5,369.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	0.00	536.90
<b>Total Parts (\$)</b>	<b>5,369.00</b>	<b>4,832.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOW	New	80.00	80.00
2	LABOUR	New	500.00	300.00
3	PRESS BODY	New	450.00	400.00
			<b>Gross Labour Cost (S\$)</b>	<b>780.00</b>
			<b>1,030.00</b>	<b>1,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >