



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 8303H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR TAIL LAMP RH	SERVICEABLE	216.20	-
1	REAR NUMBER PLATE BASE	BENT	159.60	159.60
	LESS 25% DISCOUNT		-93.95	-39.90
			281.85	119.70
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR NUMBER PLATE (SN)	BENT	25.00	25.00
1	SET REAR CAMERA WITH INSTALLATION (SN)	CRACKED	250.00	250.00
			275.00	275.00
	<b><u>LABOUR</u></b>			
	TO KNOCK DENTS ON REAR TAIL LAMP PANEL RH ND RENEW OF PARTS.		120.00	80.00
	TO DISMANTLE + REFIX BOTH REAR CARRIAGE BOX BACK DOORS LH & RH, TO REPLACE OUTER ALUMINIUM SHEETS + SUPPLY MATERIALS, TO REPAIR BACK DOOR LATCH RH ONLY, ETC.		1,450.00	1,450.00
	TO SPRAY PAINT TAILLAMP PANEL RH.		80.00	60.00
			1,650.00	1,590.00
	<b>GRAND TOTAL</b>		<b>2,206.85</b>	<b>1,984.70</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,984.70</b>

Report Ref No. CS/AGI21009206/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.