

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21009210/TTCE2

Date: 24/06/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00007272000  
Claimant Vehicle No: PC5492A Insured Vehicle No: SMJ6399D  
Date of Loss: 25/08/2021 Nature of Claim: TP Claim No: SNM21D204901/C02/TAYHP

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC5492A  
Make & Model: TOYOTA HIACE, 3.0 COMMUTER GL (A) Engine No: 1KD2656696  
Reg. Date: 14/12/2016 (Man. Year: 2016) Chassis No: KDH2230029881  
Colour: White Odometer: 255758 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,772.12	3,020.75	10,751.37	78.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,700.00	1,550.00	6,150.00	79.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>21,472.12</b>	<b>4,570.75</b>	<b>16,901.37</b>	<b>78.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,650.00</b>		
<b>(S\$)</b>	21,472.12	3,650.00	17,822.12	83.00
<b>+ GST 7.00/7.00% (S\$)</b>	1,503.05	255.50	1,247.55	83.00
<b>Nett Amount (S\$)</b>	<b>22,975.17</b>	<b>3,905.50</b>	<b>19,069.67</b>	<b>83.00</b>

### INSPECTION

Date of Assignment: 30/05/2022  
Date Inspected: 06/09/2021 Inspected At: 56 Loyang Way, #04-04 Loyang Enterprise Building  
Estimated Period of Repair: 6.0 days Repairer: AP Automotive Services Pte Ltd (HQ)

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 24 Jun 2022)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 COMMUTER GL (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC5492A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,985.00 FL	*1,750.00 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	145.50 FL	*145.50 FL
3	1		*TAILGATE LOGO - TOYOTA	Necessary	66.00 FL	*66.00 FL
4	1		*TAILGATE LOCK	Not Necessary	275.00 FL	*- FL
5	1		*TAILGATE LOCK COVER	Not Necessary	51.00 FL	*- FL
6	1		*TAILGATE LOCK CATCH	Not Necessary	62.00 FL	*- FL
7	1		*TAILGATE INNER BOARD	Cracked	203.00 FL	*203.00 FL
8	2		*TAILGATE HINGE L+R	Not Necessary	150.00 FL	*- FL
9	2		*TAILGATE DAMPER L+R	Not Necessary	434.00 FL	*- FL
10	2		*TAILGATE STOPPER L+R	Not Necessary	50.00 FL	*- FL
11	1		*TAILGATE WEATHERSTRIP	Cut	455.00 FL	*329.50 FL
12	2		*TAIL LAMP L+R	Not Necessary	600.00 FL	*- FL
13	2		*TAIL LAMP PANEL L+R	Not Necessary	2,780.00 FL	*- FL
14	1		*REAR BUMPER	Deformed	475.00 FL	*475.00 FL
15	2		*REAR SIDE BUMPER L+R	Not Necessary	226.00 FL	*- FL
16	2		*REAR SIDE BUMPER RETAINER L+R	Not Necessary	63.00 FL	*- FL
17	1		*REAR BUMPER RETAINER L+R	Not Necessary	60.00 FL	*- FL
18	1		*REAR FENDER AIRVENT RH	Not Necessary	58.00 FL	*- FL
19	1		*REAR FENDER COWLING RH	Not Necessary	193.00 FL	*- FL
20	1		*END PANEL INNER	Not Necessary	897.00 FL	*- FL
21	1		*END PANEL OUTER	Bent	512.00 FL	*512.00 FL
22	1		*END PANEL TOP GARNISH	Not Necessary	246.00 FL	*- FL
23	1		*FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
24	1		*EXHAUST PIPE	Not Necessary	474.00 FL	*- FL
25	2		*SET EXHAUST MOUNTING	Not Necessary	118.00 FL	*- FL
26	1		*EXHAUST HEAT SHIELD	Not Necessary	91.00 FL	*- FL
27	1		*TAILGATE WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
28	1		*TAILGATE STICKER - 70KM/H	Necessary	80.00 FS	*30.00 FS
29	1		*TAILGATE STICKER - OPEN	Not Necessary	80.00 FS	*- FS
30	1		*TAILGATE STICKER - EMERGENCY EXIT	Necessary	100.00 FS	*30.00 FS
31	1		*TAILGATE INNER BOARD CLIPS	Necessary	100.00 FS	*20.00 FS
32	1		*REAR NUMBER PLATE	Not Necessary	120.00 FS	*- FS
33	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
34	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
35	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
36	2		*TAIL LAMP PANEL SEALANT	Not Necessary	240.00 FS	*- FS
37	1		*END PANEL SEALANT	Necessary	200.00 FS	*40.00 FS
38	1		*END PANEL INNER PANEL SEALANT	Not Necessary	250.00 FS	*- FS
39	1		*FLOOR PANEL TOP BOARD WITH MAT	Not Necessary	4,000.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>16,439.50</b>	<b>3,891.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,667.38	870.25
<b>Total Parts (\$\$)</b>	<b>13,772.12</b>	<b>3,020.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ON AFFECTED AREAS	New	2,400.00	600.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,600.00	600.00
3	TO RNR REAR WINDSCREEN	New	400.00	120.00
4	TO RNR REAR EXHAUST	New	250.00	0.00
5	TO CHECK WIRING AND TAILLAMP FUNCTION	New	150.00	30.00
6	TO RNR REAR TRIM AND UPHOLSTERY	New	400.00	60.00
7	TO CHECK WATER LEAK	New	150.00	20.00
8	TO RNR FLOOR PANEL TOP BOARD	New	600.00	0.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
10	TO RNR REAR TAILGATE MECHANISM	New	400.00	60.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
12	TO PERFORM RUST PROOFING	New	600.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>7,700.00</b>	<b>1,550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >