

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21009216/GTF3N2**Date:** 28/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993682
Claimant Vehicle No :	SGP3132R	Insured Vehicle No :	GBK8166X
Date of Loss:	30/08/2021	Nature of Claim:	TP
		Claim No:	8382613543SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGP3132R	Engine No:	FA20A894743
Make & Model:	SUBARU FORESTER, 2.0 (A)	Chassis No:	JF1SJGK85GG069690
Reg. Date:	28/04/2016 (Man. Year: 2016)	Odometer:	127951 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	01/09/2021	Merlin Motor Works (HQ)
Date Inspected:	02/09/2021 Inspected At:	BLK 10 #03-13 AMK AUTOPOINT ANG MO KIO
		INDUSTRIAL PARK 2A
		Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$65,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT RH HEADLAMP ASSY	Cut	0.00 F	*- F
4	1		*BONNET	Repair	0.00 F	*- F
5	1		*AIR DUCT	Cut	0.00 F	*- F
6	1		*FRT RH FENDER INNER SHIELD	Bent	0.00 F	*- F
7	1		*FRT RH FENDER	Buckled	0.00 F	*- F
8	1		*FRT RH WHEEL RIM	Cut	0.00 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >