

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG21009217/UVF3E2

Date: 24/09/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001301120
Claimant Vehicle No :	GBF7149D	Insured Vehicle No :	GBE5715M
Date of Loss:	29/08/2021	Nature of Claim:	TP
		Claim No:	261994

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF7149D		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30014588N
Reg. Date:	21/02/2017 (Man. Year: 2016)	Chassis No:	JN1SC2F24Z0859202
Colour:	Gold	Odometer:	82297 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/70 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	Toyo 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,430.80	2,320.02	6,110.78	72.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	1,210.00	2,120.00	63.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,760.80	3,530.02	8,230.78	69.98
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	11,760.80	2,800.00	8,960.80	76.19
+ GST 7.00/7.00% (\$\$)	823.26	196.00	627.26	76.19
Nett Amount (\$\$)	12,584.06	2,996.00	9,588.06	76.19

INSPECTION

Date of Assignment:	06/09/2021		
Date Inspected:	01/09/2021	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Sep 2021)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF7149D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DROP SIDEGATE O/S	Dented / Bent	2,488.10 F	*1,901.00 FL
2	1		*DROP SIDEGATE LOWER MEMBER O/S	Repair	878.10 F	*- FL
3	1		*REAR MUDGUARD FRT O/S	Distorted	233.50 F	*145.00 FL
4	1		*REAR MUDGUARD REAR O/S	Distorted	233.50 F	*145.00 FL
5	1		*REAR MUDFLAP O/S	Distorted	166.00 F	*123.50 FL
6	1		*TAILLAMP O/S (SCRATCHED)	Not Consistent With The Impact	208.80 F	*- FL
7	1		*TAILGATE LOCK LATCH O/S	Bent	199.20 F	*142.30 FL
8	1		*TAILGATE LOWER L BRACKET O/S	Repair	245.00 F	*- FL
9	1		*TAILGATE LOWER L BRACKET RUBBER O/S	Torn	168.50 F	*121.00 FL
10	1		*REAR SHOCK ABSORBER O/S	Not Necessary	205.00 F	*- FL
11	1		*REAR WHEEL SHAFT O/S	Not Necessary	655.10 F	*- FL
12	1		*REAR AXLE BEAM	Not Necessary	2,200.00 F	*- FL
13	1		*REAR WHEEL OUTER RIM O/S	Repair	50.00 FS	*- FS
14	1		*DROP SIDEGATE TOP RAILING O/S	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,430.80	2,577.80
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	257.78
Total Parts (\$\$)	8,430.80	2,320.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	30.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
4	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	New	380.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	500.00
6	TO PUTTY & SPRAY PAINTING	New	1,500.00	600.00
Gross Labour Cost (\$\$)			3,330.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >