


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB327T  
Ref. No : BUS/08/16/7029  
Reg. Date : 16/10/2012  
Vehicle Type : BUS -12M  
Make : MAN  
Model : MAN  
Name of Driver : Anandan A/L Rengasamy  
Type of Accident : SIDE SWIPE  
Date / Time of Accident : 21/08/2016 03:03:00 PM  
Accident Reported Date / Time : 22/08/2016 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : IDAC  
Vehicle is Towed Back? : No  
Towed Back Date/Time : 01/01/2000  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024091510  
Special Instruction to ARC,if any :  
SMB327T - RIGHT VIEW MIRROR COVER SCRATCHES  
PC3500Z (TP) - LEFT WINDOW PANEL BROKEN  
Prepared Date : 23/08/2016 05:19:15 PM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : WMAA22ZZ1C7001460

Mileage :

0

Work Shop :

Repair Completed Date / Time : 01/01/2000

**Summary of Repair Estimates****Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges : 265.00

132.50

Total Spray Painting Charges : 0.00

0.00

Total Material Charges : 896.33

896.33

Other Charges : 0.00

-50.00

**TOTAL : 1,161.33****978.83****Lum Sum Total : 1,150.00****1,000.00**

No. of Repair Days : 1.00


0.50

Prepared / Adjusted By :

Sebastian Yeang

Arc / Surveyor Sign Off Date : 12/09/2017 02:57:55 PM

31/08/2017 02:15:26 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 13/08/2017 07:17:30 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	265.00	132.50
<b>Total Labour</b>	<b>265.00</b>	<b>132.50</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Spray Painting &amp; Panel Beating</b>		

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	0.00	-50.00
<b>Total Other Costs</b>	<b>0.00</b>	<b>-50.00</b>

# Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
4001M01-ACCE467	RIGHT	6010161	FRONT VIEW MIRROR RH	1	1,244.90	10.00	1,120.41	Replace	Replace	No <i>CRK</i>
TOTAL MATERIALS							1,120.41	1,120.41		
TOTAL MATERIALS(Discounted)							896.33	896.33		

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

$$\begin{array}{r}
 1120.41 \\
 + \quad 132.56 \\
 \hline
 1252.97 \\
 - 20\% \\
 \hline
 1002.32
 \end{array}$$

4/5 : \$ 1000

Sebastian 13/9/2017