

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009220/KGA3Q2
Date: 06/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993682
Claimant Vehicle No :	SJA8572P	Insured Vehicle No :	GBK3458L
Date of Loss:	30/08/2021	Nature of Claim:	TP
		Claim No:	6917025159SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJA8572P		
Make & Model:	MERCEDES-BENZ E200K, 1.8 (A)	Engine No:	27195630958871
Reg. Date:	26/12/2007 (Man. Year: 2007)	Chassis No:	WDB2110412B221257
Colour:	Metallic Dark Blue	Odometer:	200910 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,919.20	6,523.10	7,396.10	53.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	1,440.00	1,930.00	57.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,289.20	7,963.10	9,326.10	53.94
Approved Total (Overridden) (S\$)		6,300.00		

Nett Amount (S\$)	17,289.20	6,300.00	10,989.20	63.56
+ Car Rental (5.0 x S\$130.00/day) (S\$)		650.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		6,957.49		

INSPECTION

Date of Assignment: 01/09/2021

Date Inspected: 20/09/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Tropical Tech Automobile Services
 BLK 5030 Ang Mo Kio Avenue 3, #01-201 Industrial Park 2
 Singapore 569535

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	1,349.00 FL	*1,280.00 FL
2	2		*FRONT BUMPER CHROME MOULDING	Necessary	324.00 FL	*324.00 FL
3	1		*FRONT LICENSE PLATE GARNISH	Dented	311.00 FL	*311.00 FL
4	2		*FRONT BUMPER SIDE BRACKET	Serviceable	162.00 FL	*- FL
5	1		*FRONT BUMPER SPONGE (CENTRE)	Serviceable	108.00 FL	*- FL
6	1		*FRONT BUMPER SPONGE (SIDE)	Serviceable	162.00 FL	*- FL
7	1		*FRONT BUMPER FRAME (CENTRE)	Serviceable	54.00 FL	*- FL
8	1		*FRONT BUMPER FRAME (SIDE)	Cracked	162.00 FL	*162.00 FL
9	2		*SET FRONT SEAT HEAD REST	Serviceable	2,396.00 FL	*- FL
10	1		*FRONT LICENSE SMART PLATE }	Dented	35.00 FS	*35.00 FS
11	1		*FRONT LICENSE SMART PLATE CASING }		0.00 FS	*- FS
12	1		*REAR BOOT	Repair	1,899.00 FL	*- FL
13	1		*REAR BOOT 3RD BRAKE LAMP	Cracked	373.00 FL	*373.00 FL
14	1		*REAR BOOT EMBLEM	Necessary	49.00 FL	*49.00 FL
15	3		*REAR BOOT EMBLEM GROMMET	Necessary	18.00 FL	*18.00 FL
16	1		*REAR BOOT E200 DESIGNATION	Necessary	119.00 FL	*119.00 FL
17	1		*REAR BOOT KOMPRESSOR DESIGNATION	Necessary	168.00 FL	*168.00 FL
18	1		*REAR BOOT LOCK	Dented	446.00 FL	*446.00 FL
19	2		*REAR TAIL LAMP	Serviceable	1,080.00 FL	*- FL
20	8		*REAR TAIL LAMP GARNISH CLIP	Not Necessary	72.00 FL	*- FL
21	1		*REAR BUMPER	Buckled / Cracked	1,808.00 FL	*1,680.00 FL
22	1		*REAR BUMPER CHROME MOULDING (CENTRE)	Necessary	284.00 FL	*185.00 FL
23	2		*REAR BUMPER CHROME MOULDING (SIDE)	Necessary	410.00 FL	*300.00 FL
24	1		*SET REAR BUMPER PARKTRONIC SENSOR KIT	Dented	280.00 FL	*280.00 FL
25	2		*REAR BUMPER LOWER BRACKET	Cracked	60.00 FL	*60.00 FL
26	2		*REAR BUMPER SIDE BRACKET	Serviceable	270.00 FL	*- FL
27	1		*REAR BUMPER FRAME (CENTRE)	Cracked	351.00 FL	*280.00 FL
28	1		*REAR BUMPER REINFORCEMENT	Bent	769.00 FL	*582.00 FL
29	1		*REAR TAIL PIPE BRACKET	Repair	95.00 FL	*- FL
30	1		*REAR LICENSE SMART PLATE }	Serviceable	35.00 FS	*- FS
31	1		*REAR LICENSE SMART PLATE CASING }		0.00 FS	*- FS
32	1		*FRONT LH HEAD LAMP	Mtg Cracked	540.00 FL	*540.00 FL
33	1		*RADIATOR	Serviceable	1,079.00 FL	*- FL
34	1		*MB COOLANT	Not Necessary	27.00 FS	*- FS
35	1		*REAR TAIL LAMP GARNISH (RH)	Cracked	52.00 FL	*52.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR BUMPER TOWING COVER	Serviceable	108.00 FL	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					15,455.00	7,244.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					1,535.80	720.90
Total Parts (\$\$)					13,919.20	6,523.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND TRANSFER FRONT BUMPER NECESSARY ATTACHMENT SPART PART ITEMS }	New	400.00	220.00
2	REMOVE AND REFIT FRONT BUMPER ,FRONT BUMPER CHROME MOULDINGS,FRONT LICENCE PLATE GARNISH ,FRONT BUMPER SIDE BRACKETS ,FRONT BUMPER SPONGE (CENTRE) ,FRONT BUMPER SPONGE (SIDE),FRONT BUMPER FRAME (CENTRE) ,FRONT BUMPER FRAMES (SIDE) }	New	0.00	0.00
3	REMOVE AND REFIT FRONT HEAD REST	New	200.00	100.00
4	TO CHECK & REFIT FRONT HEAD LAMP WIRING HARNESS	New	120.00	0.00
5	TUFF KOTE FRONT DAMAGED PORTION	New	150.00	0.00
6	PUTTY /PRIMER APPLICATION SPRAY PAINTING FRONT BUMPER ,FRONT BUMPER LICENSE PLATE GARNISH	New	400.00	240.00
7	REMOVE AND TRANSFER REAR BOOT NECESSARY ATTACHMENTS SPARE PART ITEMS }	New	800.00	400.00
8	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENTS SPARE PART ITEMS }	New	0.00	0.00
9	REMOVE & REFIT REAR BOOT ,REAR BOOT 3RD BRAKE LAMP ,REAR BOOT LOCK ,REAR TAIL LAMPS,REAR TAIL LAMP GARNISH CLIP ,REAR BUMPER ,REAR BUMPER CHROME MOULDING (CENTRE),REAR BUMPER CHROME MOULDINGS (SIDE) ,REAR BUMPER PARKTRONIC SENSOR KITS ,REAR BUMPER LOWER BRACKETS ,REAR BUMPER SIDE BRACKETS ,REAR BUMPER FRAME (CENTRE) ,REAR BUMPER REINFORCEMENT ,REAR TAIL PIPE BRACKET }	New	0.00	0.00
10	PANEL /BEATING REAR END PANEL ,HEAT /WELD/BEATING/PULL/STRAIGHTEN/ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK }	New	0.00	0.00
11	UNDER COATING ON REAR DAMAGED PORTION	New	300.00	0.00
12	PUTTY/PRIMER APPLICATION ,SPRAY PAINTING REAR BOOT ,REAR BOOT LICENSE PLATE GARNISH ,REAR END PANEL,REAR BUMPER ,REAR BUMPER PARKTRONIC SENSORS	New	1,000.00	480.00
Gross Labour Cost (\$\$)			3,370.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >