

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21009221/BEA3Q2
Date: 29/12/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SBU1001G	Insured Vehicle No :	SME1383H
Date of Loss:	29/08/2021	Nature of Claim:	TP
		Claim No:	6599292338SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBU1001G	Engine No:	1ZRX551661
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Chassis No:	MR053REH104545390
Reg. Date:	29/03/2016 (Man. Year: 2015)	Odometer:	31858 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,525.50	3,706.22	4,819.28	56.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	1,590.00	2,360.00	59.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,475.50	5,296.22	7,179.28	57.55
Approved Total (Overridden) (S\$)		4,200.00		

(S\$)	12,475.50	4,200.00	8,275.50	66.33
+ GST 7.00/7.00% (S\$)	873.29	294.00	579.29	66.33
Nett Amount (S\$)	13,348.79	4,494.00	8,854.79	66.33
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,041.45		

INSPECTION

Date of Assignment: 01/09/2021

Date Inspected: 02/09/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
 Singapore 575722

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,093.00 FL	*781.10 FL
2	1		*BOOTLID LOGO	Necessary	85.50 FL	*68.00 FL
3	1		*BOOTLID EMBLEM COROLLA	Necessary	68.00 FL	*32.00 FL
4	1		*BOOTLID EMBLEM ALTIS	Necessary	65.37 FL	*55.00 FL
5	1		*BOOTLID OUTER CHROME GARNISH	Cut	415.60 FL	*202.50 FL
6	2		*BOOTLID LAMP	N/S Broken / O/S Cut	970.60 FL	*656.00 FL
7	1		*BOOTLID INNER LOCK	Not Damaged	298.70 FL	*- FL
8	1		*BOOTLID INNER LOCK STRIKER	Not Damaged	65.00 FL	*- FL
9	1		*BOOTLID INNER TRIM BOARD	Not Damaged	352.80 FL	*- FL
10	1		*BOOTLID WEATHERSTRIP	Not Damaged	298.60 FL	*- FL
11	1		*BOOTLID ANTENNA SENSOR	Not Damaged	218.40 FL	*- FL
12	1		*REAR BUMPER	Broken	885.90 FL	*639.80 FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	236.40 FL	*130.00 FL
14	1		*REAR BUMPER INNER SPONGE	No such part	141.80 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Dented	487.30 FL	*398.70 FL
16	2		*REAR BUMPER SIDE BRACKET	Not Damaged	171.20 FL	*- FL
17	2		*REAR BUMPER REFLECTOR	Not Damaged	187.20 FL	*- FL
18	1		*REAR END PANEL	Dented	762.10 FL	*645.30 FL
19	1		*REAR END PANEL TOP GARNISH	Broken	268.00 FL	*185.99 FL
20	2		*REAR FENDER INNER TRIM BOARD	Not Damaged	916.00 FL	*- FL
21	1		*TAILLAMP	O/S Broken	1,189.20 FL	*411.90 FL
22	1		*TAILLAMP LOWER BRACKET	O/S Broken	164.00 FL	*82.00 FL
23	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
24	1		*BOOTLID SEALANT	Necessary	100.00 FS	*40.00 FS
25	1		*BOOTLID OUTER CHROME GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
26	1		*BOOTLID LAMP SEAL	Necessary	120.00 FS	*60.00 FS
27	2		*BOOTLID LAMP CLIPS	Necessary	100.00 FS	*20.00 FS
28	1		*BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
30	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
32	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
33	2		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	100.00 FS	*- FS
34	1		*TAILLAMP SEAL	O/S Necessary	120.00 FS	*30.00 FS
35	2		*TAILLAMP CLIPS	Necessary (1 PCS ONLY)	100.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					10,860.67	4,778.29
- List Item Discount on L Items 25.00/25.00% (S\$)					2,335.17	1,072.07
Total Parts (S\$)					8,525.50	3,706.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R BOOTLID COMPONENT	New	150.00	80.00
2	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
3	DIAGNOSTIC & RESET FAULT CODE	New	300.00	0.00
4	UPHOLSTERY	New	300.00	0.00
5	CHECK WIRING	New	100.00	50.00
6	PANEL BEATING	New	1,400.00	800.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,400.00	600.00
Gross Labour Cost (S\$)			3,950.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >