

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009222/AEA3Q2
Date: 28/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100460892
Claimant Vehicle No :	SLE1111M	Insured Vehicle No :	SDX5115X
Date of Loss:	31/08/2021	Nature of Claim:	TP
		Claim No:	3179960475SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE1111M		
Make & Model:	TOYOTA VELLFIRE, 2.5 ELEGANCE MOONROOF (A)	Engine No:	2AR2177373
Reg. Date:	26/11/2020 (Man. Year: 2019)	Chassis No:	JTNGF3DH608023231
Colour:	White	Odometer:	8328 km
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,108.00	1,511.25	3,596.75	70.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	850.00	800.00	48.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,758.00	2,361.25	4,396.75	65.06
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		

Nett Liability (S\$)**2,668.70**INSPECTION

Date of Assignment: 01/09/2021

Date Inspected: 01/09/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premium Carz Services Pte Ltd (HQ)
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki
Singapore 417883**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,800.00 FL	*707.00 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Necessary	135.00 FL	*135.00 FL
3	1		*REAR BUMPER SIDE RETAINER LH	Necessary	135.00 FL	*135.00 FL
4	1		*REAR BUMPER REFLECTOR RH	Not Necessary	120.00 FL	*- FL
5	1		*REAR BUMPER TOW HOOK COVER RH	Not Necessary	55.00 FL	*- FL
6	1		*REVERSE SENSOR (3 PCS)	Damaged (2 PCS ONLY)	1,605.00 FL	*784.00 FL
7	1		*TAIL GATE	Repair	1,985.00 FL	*- FL
8	1		*TAIL GATE WEATHERSTRIP	Not Necessary	357.00 FL	*- FL
9	1		*TAIL GATE VELLFIRE EMBLEM	Necessary	98.00 FL	*98.00 FL
10	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
11	1		*TAIL GATE GLASS MOULDING	Not Necessary	178.00 FL	*- FL
12	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
13	8		*TAIL GATE TRIMBOARD CLIP	Not Necessary	40.00 FS	*- FS
14	1		*SEALANT	Not Necessary	80.00 FS	*- FS
15	4		*REVERSE SENSOR BRACKET	Necessary	116.00 FL	*116.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,754.00	2,005.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,646.00	493.75
Total Parts (\$\$)	5,108.00	1,511.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	60.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	600.00	300.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	800.00	500.00
4	TO SPRAY ANTI-RUST UNDERCOAT	New	40.00	20.00
5	TO REMOVE AND REFIT TAIL GATE GLASS	New	150.00	0.00
Gross Labour Cost (\$)			1,650.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >